

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for well proposals.)

1. oil ☒ well ☐ gas well ☐ other
2. NAME OF OPERATOR
Merrion Oil & Gas Corporation
3. ADDRESS OF OPERATOR
P. O. Box 1017, Farmington, New Mexico 87499
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 2000' FNL and 820' FWL
AT TOP PROD. INTERVAL: Same
AT TOTAL DEPTH: Same
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

- TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
CHANGE ZONES ☐
ABANDON* ☐
(other) TD, Casing ☐

SUBSEQUENT REPORT OF:

- ☐
☐
☐
☐
☐
☐
☐
☐
☐

RECEIVED

SEP 29 1983

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

DEPARTMENT OF THE INTERIOR
FARMINGTON RESOURCE AREA

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

TD 9/23/83, 5921'.

Ran 145 joints, 5941.35', 4-1/2", 10.5 #/ft. casing @ 5021' KB with 225 sx Class H (275 cu. ft.) with 2% gel. 700 sx Class B (1442 cu. ft.) with 2% Thrifty Light. 100 sx Class H (122 cu. ft.) 2% Gel. Circulated 4 Bbls to surface.

RECEIVED

SEP 29 1983

Subsurface Safety Valve: Manu. and Type

Set @

Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED John A. Hill TITLE Operations Manager DATE 9/26/83

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

ACCEPTED FOR RECORD

SEP 30 1983

*See Instructions on Reverse Side

FARMINGTON RESOURCE AREA

BY

SMH

NMOC