

MERRION OIL & GAS CORPORATION

Canyon Largo Unit 341
990' FSL and 1850' FWL
Sec. 1, T24N, R7W
Rio Arriba Co., New Mexico

SLOPE TESTS


<u>Depth</u>	<u>Hole Deviation</u>
232	1-1/4
742	1-1/2
1241	2-1/2
1356	2
1788	2-1/2
2045	1
2490	1
2992	1
3496	3/4
3995	1
4529	1-1/4
5028	2
5525	1-1/4
5920	3/4

RECEIVED
SEP 24 1984
OIL CON. DIV.
DIST. 3

State of New Mexico)
County of San Juan) ss

I, Steve S. Dunn, being first duly sworn, depose and state that the above and foregoing depth and hole deviation figures are true and correct to the best of my information and belief.

Subscribed and sworn before me this 17th day of September, 1984



Cheryl N. Simkins
Notary Public

My Commission Expires March 25, 1988

