

Clark #13

I-6-24N-3W

J. FELIX HICKMAN

F

30-039-23633

12-18-84

F. Loc. 1845/S; 410/E Elev. 7010 GL Spd. _____ Comp. _____ TD _____ PB _____
 Cu. ft. Cu. ft. Cu. ft.
 Casing S. @ W Sx. Int. @ W Sx. Pr. @ W Sx. T. @ T Gas
 Csg. Perf. Prod. Stim.

T
R
A
N
S

80/D 1st Del. Gas
 I.P. MCF/D After Hrs. SICP PSI After Days GOR 1st Del. Oil

TOPS		NiTD X	Well Log	TEST DATA							
Ojo Alamo		C - 103	Plat X	Schd.	PC	Q	PW	PD	D	Ref.No.	
Kirtland		C - 104	Electric Log								
Fruitland			C - 122								
Pictured Cliffs		Ditr	Dfa								
Chacra		Datr	Dac								
Cliff House											
Menefee											
Point Lookout											
Mancos											
Gallup											
Greenhorn											
Dakota											
Entrada											
			Acres 191.23								

P
o
o

W. Lin. Gal. DakCo. RA S 6 T 24N R 3W U I Oper. J. Felix Hickman

Lse. Clark

No. 13

Caller Service 4104
Farmington, New Mexico 87499

SEP 11 1986

CERTIFIED--RETURN RECEIPT REQUESTED


J. Felix Hickman
P.O. Box 208
Farmington, NM 87499

Gentlemen:

Enclosed are your Applications for Permit to Drill (APDs) wells numbered 12 and 13 Clark, NE sec. 5 and SE sec. 6, T. 24 N., R. 3 W., Rio Arriba County, New Mexico, lease NM-03011. The subject APDs are rescinded and returned due to drilling not being commenced within one year of the approval date.

You are required to request surface rehabilitation instructions from this Office if construction activities occurred on the referenced drill sites. If this office does not receive comment within 15 days, we will presume that no construction occurred. Later discovery that construction activities have in fact occurred, will result in an assessment.

Sincerely,



FORRON Fellows
Area Manager

2 Enclosures

cc:
NMOCD

RECEIVED
SEP 12 1986
OIL CON. DIV.
DIST. 3

ABANDONED LOCATION

