

MERRION OIL & GAS CORPORATION

Canyon Largo Unit 308  
Sec. 5, T24N, R6W  
Rio Arriba Co., New Mexico

SLOPE TESTS


| <u>Depth</u> | <u>Hole Deviation</u> |
|--------------|-----------------------|
| 222          | 1                     |
| 516          | 3/4                   |
| 1002         | 3/4                   |
| 1321         | 1/2                   |
| 1668         | 3/4                   |
| 2185         | 1                     |
| 2736         | 1/2                   |
| 3071         | 1                     |
| 3551         | 3/4                   |
| 3724         | 1                     |
| 4243         | 1-1/4                 |
| 4765         | 2                     |
| 5175         | 1-1/4                 |

**RECEIVED**  
JUL 30 1985  
OIL CON. DIV.]  
DIST. 3

State of New Mexico )  
                                  ) ss  
County of San Juan )

I, Steve S. Dunn, being first duly sworn, depose and state that the above and foregoing depth and hole deviation figures are true and correct to the best of my information and belief.

Subscribed and sworn before me this 11th day of April, 1985.

  
Notary Public

My Commission Expires Dec. 11, 1985