
UNITED STATES DEPARTMENT OF THE INTERIOR	5. LEASE Contract 126
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME Jicarilla Apache
SUNDRY NOTICES AND REPORTS ON WELLS  (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir, Use Form 9–331–C for such proposals.)	7. UNIT AGREEMENT NAME NA
1 oil gas —	8. FARM OR LEASE NAME Apache
2. NAME OF OPERATOR	9. WELL NO
Cotton Petroleum Corporation  3. ADDRESS OF OPERATOR	10. FIELD OR WILDCAT NAME Lindrith Gallup Dakota W.
3773 Cherry Crk Dr No., #750, Den, CO 80209 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec 1 T24N R4W
AT SURFACE: 680' FSL 935' FEL AT TOP PROD. INTERVAL: AT TOTAL DEPTH:	12. COUNTY OR PARISH 13. STATE Rio Arriba NM 14. API NO.
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA	30-039-23661  15. ELEVATIONS (SHOW DF, KDB, AND WD) 7001' GR
MULTIPLE COMPLETE	Change on Form 9-330.)  1 2 1985  AND MANAGEMENT
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is different measured and true vertical depths for all markers and zones pertinent. The well was spud at 2:30 pm on March 7, 1985 a 12-1/4" surface hole to 397', ran 397' of 8	irectionally drilled, give subsurface locations and it to this work.)*  5 using Aztec Rig 124. Drilled 8-5/8" 24# K55 ST&C casing,
land casing at 396', Cement w/260 sxs, 1.26	yield, 327.6 cuft Class B

cement + 2% CaCl, 1/4#/sxs Cello flake, circulate out.

prosure tested 1000#, 30 minutes



OIL CON. DIV.

Subsurface Safety Valve: Manu. and Ty	/pe	Set @	Ft.
18. I hereby certify that the foregoing	is true and correct		
SIGNED WE WOOD	TITLE Division	Prod. MgrDATEJune 5, 1985	
	(This space for Federal or S	State office use)	
APPROVED BY	TITLE	DATE	