

STATE OF NEW MEXICO

ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE

TONEY ANAYA

1000 RIO BRAZOS ROAD AZTEC, NEW MEXICO 87410 (505) 334-6178

April 22, 1985

Bus-Rex, Inc. P.O. Box 50325 Tucson, AZ 85703

Re: Cido #4 A-9-25N-1E Cido #5 G-9-25N-1E Cido #6 P-4-25N-1E Cido #7 H-9-25N-1E Denny #2 P-4-25N-1E

Gentlemen:

A recent field inspection and a review of well records reveal the referenced wells are in violation of several OCD Rules and Regulations.

Cido #4 - No well sign.

Cido #5 - No reports after spud date. No well sign.

Cido #6 - Has been completed - no reports, including spud date.

Cido #7 - No well sign.

Denny #2 - No completion report. Has been plugged without an approved C-103 as intent to P&A. Dry hole marker is not rigid and is not marked legally.

You are hereby directed to initiate immediate remedial activity and file delinquent reports.

If you have any questions, please contact this office.

Yours truly

Charles Gholson

Oil & Gas Inspector

CG/dj

xc: Richard Stamets

Well Files