



STATE OF NEW MEXICO  
**ENERGY AND MINERALS DEPARTMENT**  
OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE

TONY ANAYA  
GOVERNOR

1000 RIO BRAZOS ROAD  
AZTEC, NEW MEXICO 87410  
(505) 334-6178

January 9, 1985

Chet Oakley  
Bus Rx, Inc. dba Cido Oil Co.  
P.O. Box 50325  
Tucson, AZ 85703

Re: CIDO #4 A-9-25N-1E  
CIDO #5 G-9-25N-1E  
CIDO #6 P-4-25N-1E  
CIDO #7 H-9-25N-1E✓

Dear Chet:

A recent review of well records reveal the referenced wells have conflicting reported information:

CIDO #4 - Temporary abandonment has expired - what are your future intentions?

CIDO #5 - C-101 states using 8" casing, spud sundry C-103 states 10" casing and the completion C-105 states 8 5/8" casing, which is correct?


CIDO #6 - C-101 states 10" surface casing  
C-103 dated 4-1-85 changes to 8 5/8"  
C-103 dated 7-11-85 states 10"  
C-105 states 8". Which is correct?  
C-103 dates 7-11-85 states surface set @ 205'  
C-105 reports 200'. Which is correct?  
C-103 to deepen reports 1500' - 2670'  
C-105 reports 1900' - 2600'. Which is correct?

CIDO #7 - No well sign

Chet, please address each problem in this letter and submit corrected reports.

If you have any questions, please contact me.

Yours truly,

  
Ernie Busch

Geologist 3/Oil & Gas Inspector

xc: E. Busch

~~Operator File~~

Operator File