

F

30-039-24119

11-13-86

F. Loc. 330/N; 1900/E Elev. 7435 GL Spd. _____ Comp. _____ TD _____ PB _____
 Cu. ft. _____ Cu. ft. _____
 Casing S. _____ @ _____ W _____ Sx. Int. _____ @ _____ W _____ Sx. Pr. _____ @ _____ W _____ Sx. T. _____ @ _____
 Csg. Perf. _____ Prod. Stim. _____

T
R
A
N
S

Grav. _____ 1st Del. Gas _____
 1st Del. Oil _____
 I.P. _____ BO/D _____ MCF/D After _____ Hrs. SICP _____ PSI After _____ Days GOR _____

TOPS		NiTD X	Well Log	TEST DATA							Ref. No.
				Schd.	PC	Q	PW	PD	D		
Ojo Alamo		C-103	Plot X								
Kirtland		C-104	Electric Log								
Fruitland			C-122								
Pictured Cliffs		Ditr	Dfa								
Chacra		Datr	Dac								
Cliff House											
Menefee											
Point Lookout											
Mancos											
Gallup											
Greenhorn											
Dakota											
Entrada											
			Acres 57.99								

P
O
JitoGal-DkCo. RA S 1 T 25N R 3W U B Oper. Minel, Inc.

Loc. NZ No. 3

B-1-25N-3W

NZ #3

MINEL, INC.

SF-080566-A (WC)
3162.3-1 (016)

Caller Service 4104
Farmington, New Mexico 87499

NOV 23 1987

CERTIFIED--RETURN RECEIPT REQUESTED
P-684-171-547

Minel, Inc.
457-C Washington SE
Albuquerque, NM 87108

Gentlemen:

Enclosed is your Application for Permit to Drill (APD) for well No. 3 N-Z,
NM/4NE/4 sec. 1, T. 25 N., R. 3 W., Rio Arriba County, New Mexico, lease
SF-080566-A.

The subject APD is rescinded and returned due to drilling not being commenced
within one year of the approval date.

You are required to request surface rehabilitation instructions from this
office if construction activities occurred on the referenced drill site. If
this office does not receive comment within 30 days, we will presume that no
construction occurred. Later discovery that construction activities have in
fact occurred, may result in an assessment for noncompliance.

Sincerely,

/s/ John L. Keller

FOR Ron Fellows
Area Manager

1 Enclosure

cc:
NMOCD

RECEIVED
NOV 30 1987
OIL CON. DIV.
DIST. 3

ABANDONED LOCATION