



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe
Lease No. 078823
Unit Canyon Largo

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT <input checked="" type="checkbox"/>
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

BEALY - GOVERNMENT #1-8

April 11, 1956

Well No. 1-8 is located 990 ft. from AN line and 990 ft. from E line of sec. 8

SE 1/4, Section 8
(1/4 Sec. and Sec. No.)

25N
(Twp.)

6W
(Range)

DESM
(Meridian)

Wildcat
(Field)

Rio Arriba
(County or Subdivision)

New Mexico
(State or Territory)

(Canyon Largo Unit)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudlogging jobs, cementing points, and all other important proposed work)

8-5/8" Casing @ 93' w/75 sax (Circulated to Surface)

TD: 2800' Top Fractured Cliffs: 2676' (-3990)

Run open ended 4 1/2" Dr & equalized 55 sax cement @ 2800', pulled to 2235' and equalized 75 sax cement, 15 Ca Cl, located top of plug at 1995'. Put 15 sax in top of surface casing. Placed a marker 4' above ground & cleaned up location.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company THE SUPERIOR OIL COMPANY

Address MIDLAND, TEXAS

By L. J. Willis (L. J. Willis)

Title Petroleum Engineer

01-01-1971

01-01-1971
MOO MOO MOO
01-01-1971