SUNDRY NOTICES AND REPORTS ON WELLS	
servoir. Use rottin 3-331-C for Social proposada.	7. UNIT AGREEMENT NAME 8. FARM OR LEASE NAME
1. oil well other 2. NAME OF OPERATOR Northwest Pipeline Corporation 3. ADDRESS OF OPERATOR P.O. Box 90, Farmington, N.M. 87499 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) AT SURFACE: 1450 FSL & 1520 FWL NW/SW AT TOP PROD. INTERVAL: 1450 FSL & 1520 FWL AT TOTAL DEPTH: 1450 FSL & 1520 FWL 6. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA	Rucker Lake 9. WELL NO. #2 10. FIELD OR WILDCAT NAME Wildcat Entrada 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec 24, T25N, R2W 12. COUNTY OR PARISH 13. STATE Rio Arriba N.M. 14. API NO. 15. ELEVATIONS (SHOW DF, KDB, AND WD) 7396' KB 1983 PORCE Change of Form 19:320:6 1983 OIL CON. DIV. DIST. 3

measured and true vertical depths for all markers and zones pertinent to this work.)

Spotted 120 sx (142 cu.ft) plug 50' below top of Entrada to 50' above top of Bluff formations (8950' to 8750').

Subsurface Safety Valve: Manu. and Ty	oe	Set @ Ft.
18. I hereby certiff that the foregoing is signed Mark McCallister	TITLE Drlg Engineer (This space for Federal or State office	ACCEPTED FOR RECORD
APPROVED BY	TITLE	AUG 2 3 1983

MAM/djb/4

FARMINGTON RESOURCE AREA - FARMINGTON, NEW MEXICO 5mm