DEPARTMENT OF THE INTERIOR TO THE INTERIOR TO THE SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plus back top a different reservoir. Use "APPLICATION FOR PERMIT —" for such proposals." OTHER TOTAL TO THE TOTAL	NM-087657 6. IF INDIAN, ALLOTTEE DE TEINE NAME
OIL WELL OTHER OTH	
OIL WELL OTHER OTHER OTHER OTHER OTHER OTHER	
NAME OF OPERATOR FARMINGS SAME	7. UNIT ACREEMENT PAME
PARMILIA ALL	8. FARM OR LEASE NAME
BCO, Inc.	Escrito Gallup Unit
BCO, Inc. FARMING ON RESOURCE AREA ADDRESS OF OFFERTOR FARMINGTON, NEW MEXICO	9. WELL BO.
110 Grant Avenue Saula re, Nr. 0/301	19 (Smith 1)
LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)	10. FIELD AND POOL, OR WILDCAT
1650' FSL 710' FEL Sec. 13 T24N R8W NMPM	Escrito Gallup 11. ENC., T., E., M., OR ELE. AND BURYEY OF AREA
	13-24N-8W NMPM 12 COURTY OF PARISH 13 STATE
4. FERNIT NO. 15. ELEVATIONS (Show whether DF, RT, CR, etc.)	
7056 GR	San Juan NM
6. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Nation of Internation to:	ther Data
TEST WATER SHOT-OFF PULL OR ALTER CASING WATER SHOT-OFF	REPAIRING WELL
FRACTURE TREAT MULTIPLE COMPLETE FRACTURE TREATMENT Y	ALTERING CARING
SHOOT OR ACIDIZE ABANDONS SHOOTING OR ACIDIZING	ABANDONMENT [®]
REPAIR WELL CHANGE PLANS (Other)	
(Other) (Nork: Report results of Completion or Recomplete	of multiple completion on Well - tion Report and Log form.)
July 27, 1987 Dropped 5 bbls diesel down tubing and 5 bbls diesel Tagged bottom at 5907'. Tripped out of hole with 2-3/8" tubing). Tripped in and out of hole with 2-3/8" tubing and of PC Drillable Bridge Plug at 5870' with wire line. 2-7/8" tubing, Baker Straddle Packer, 1 joint of 2-4 joints 2-3/8" tubing between packers. Set stradfilled annulus with 37 bbls crude oil and pressure for 15 minutes. July 29, 1987 Treated 34,900 gallons of water with 175 gallons of 5950 lbs of KCL, 35 gallons LP55 Scalecheck, 700 lb 100 lbs of K-34 and 5 lbs of GBW-30. Sand water fow with 116,330 gallons of 70 quality foam, 147,500 lb standard cubic feet of nitrogen. Average treating bbls per minute. ISIP 2600, 5 min. 2170, 10 min. 2 well three hours before flowing back.	2-3/8" tubing (5875' strappeding and casing scraper. collar locator. Set Baker Tripped in hole with -3/8" tubing above and ddle packer at 5604'-5736'. tested backside to 500 PSI E TRI-S, 70 gallons of 3N, os WG-11, 50 lbs of HYG-3, cam fracked 5817'-5823' os 20-40 sand, and 1,814,350 pressure 5200 PSI at 16 foam
8. I bereby certify that the foregoing is true and correct SIGNED Elizabeth B. Keeslan TITLE Vice President (This space for Federal or State office use) AUG 1310	(Continued) BATE 8/10/57 EPTED FOR RECOID
CONDITIONS OF APPROVAL IF ANT: See Instructions on Reverse Side	WILLIAM VESOUNCE VIKEY

NMOCO
Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the

July 30, 1987 Flowed well overnight to frac tank. Released packer and swabbed well. Tripped out of hole and laid down 2-7/8" tubing. Tripped in hole with saw tooth collar and 2-3/8" tubing. Tagged sand at 5825'. Landed tubing at 5819'. Pressured up annulus to 800 PSI with 24,300 standard cubic feet of nitrogen. Swabbed well. Placed well in production to clean up.