| (May 1963) | DEPART | MENT OF THE | | SUBMIT IN TRIPLIC Other instructions of verse side) | n re | | No. 42-R1424. | |
|---|-----------------|--|----------------|---|--|---|--|--|
| | | GEOLOGICAL SURVEY | | | | SF 78301 | | |
| SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.) | | | | | | 6. IF INDIAN, ALLOTTEE OR TRIHE NAME 7. UNIT AGREEMENT NAME | | |
| | | | | | | | | |
| 2. NAME OF OPERATOR | | | | | 8. т | RM OR LEASE NA | ME | |
| Skelly Oil | | · · · · · · · · · · · · · · · · · · · | | | | ELL NO. | | |
| | | | | | | 114 | | |
| 1860 Lincoln St Denver, Colorado 80203 4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* | | | | | | TELD AND POOL, | OR WILDCAT | |
| See also space 17 below.) At surface | | | | | | Bisti Lower Gallup | | |
| 1980' FNL & 1980' FWL Section 12-24N-10W | | | | | | 11. SEC., T. R., M., OR BLE. AND SURVEY OR AREA Sec 12-24-10W | | |
| | | | | | | | | |
| 14. PERMIT NO. | | 15. ELEVATIONS (Show whether DF, RT, GR, etc.) | | | | San Juan New Mexico | | |
| | - | 68281 GR 69391 KB | | | | Juan | New Mexico | |
| 16. | Check A | ppropriate Box To I | ndicate Na | ture of Notice, Report, | or Other | Data 📑 | | |
| | NOTICE OF INTE | NTION TO: | 1 | at | BSEQUENT R | EPORT OF: | • | |
| TEST WATER SHUT-O | re | PULL OR ALTER CASING | | WATER SHUT-OFF | | REPAIRING | WELL | |
| FRACTURE TREAT | | MULTIPLE COMPLETE | | FRACTURE TREATMENT | | ALTERING (| CASING | |
| SHOOT OR ACIDIZE | | ABANDON* | | SHOOTING OR ACIDIZING | | ABANDONME | ENT* | |
| REPAIR WELL | | CHANGE PLANS | | (Other) (Note: Report r | esults of mu | ltiple completion | on Well | |
| | | well to church | all postioont | Completion or Re | completion f | teport and Log fo | orm.) | |
| proposed work. If nent to this work.) | well is direct | ionally drilled, give subs | arface locatio | details, and give pertinent us and measured and true | vertical dept | hs for all market | rs and zones perti- | |
| | | _ | _ | | 5 | | | |
| All depths sho | own are fi | rom ground leve | ÷1. | | 3 | 10 da | | |
| Ø /0 /71 _ MT & | DII Antes | Mall Service I | Init | | 2.00 2.00 2.00 2.00 2.00 2.00 2.00 2.00 | 원() 11 (12 (12 (12 (12 (12 (12 (12 (12 (12 | | |
| 8/9/71 - MI & RU Aztec Well Service Unit. Spotted cement from 5529' to 5429'. Pulled 2" tubing. | | | | | | 주 6 분 도 개 및 (| | |
| | | | | set cement plug a | t 1875 | to -1725', | cement _ | |
| went out of hol | e in cas: | ing below 2000' | • | _ | | | | |
| Set cement plug from 1875' to 1725' inside and outside of $5\frac{1}{2}$ " casi | | | | | | | | |
| Perforated 52" | casing a | t 1300". | | | dan Tal | | 4 /20 /21 | |
| Set cement plug | ; irom 130 | JO: to 1200: 11 | iside and | d outside $5\frac{1}{2}$ " cas | Tug. 10 | o combrere | 11/50/71 | |
| This well is h | neing left | t in condition | to be pr | roduced for water | source | | · 基本数据。 | |
| Inito Hotal to | 7026 2.02 | • • • • • • • • • • • • • • • • • • | TO TO FE | | | | | |
| An assignment t | to the Br | ethern in Chris | st Missio | on, Inc Bloomf | ield, N | ew Mexico | will be | |
| made by Skelly | Oil Compa | any on the term | ination | date of the East | Bisti | Jnit. | Engales de la Companya de la Company | |
| • | | | | _ | E PIZE | | | |
| | | | | 6 | | | | |
| | | | | / K | Luly | CD3 | | |
| | | | | / | . | | | |
| | | | | (D) | EC 10 1 | 971 | f _ | |
| | 1_ | | | \ MI | CON C | one / | <u> </u> | |
| 18. I hereby certify that | the foregoing | is true and correct | | | CON. C. | | | |
| SIGNED Le. L | 15 Pal | т | ITLE Lea | ad Clerk | 1010 II. 3 | DATE Dec. | .8, 1971 | |
| (This space for Fede | ral or State of | fice use) | | · | • | , | | |
| APPROVED BY | | ·Т | ITLE | | | DATE | | |
| CONDITIONS OF A | PROVAL, IF | | <u> </u> | | | | ·. • | |