

(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office **Santa Fe**  
Lease No. **081221-B**  
Unit **Bolack**

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

October 3, 1962

Well No. **1** is located **1080** ft. from **{N}** line and **1920** ft. from **{E}** line of sec. **9**  
**SW/4 SE/4 Sec. 9** **26N** **1W** **N.M.P.M.**  
(¼ Sec. and Sec. No.) (Twp.) (Range) (Meridian)  
**Wildcat** **Rio Arriba** **New Mexico**  
(Field) (County or Subdivision) (State or Territory)


The elevation of the derrick floor above sea level is **7770** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

6-29-62 TD 310' RKB. Set 9 joints 292.18' of 13-3/8" OD 38# H-40 casing at 306.48' RKB with 350 sacks cement, 2% calcium chloride.

6-30-62 Pressured up on casing to 500#. No decrease in pressure in one hour.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **BOLACK, GREER ET AL**  
Address **158 Petroleum Center Bldg.**  
**Farmington, New Mexico**

By *Albert Greer*  
Title \_\_\_\_\_