

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division

Sundry Notices and Reports on Wells


| | |
|---|--|
| <p>1. Type of Well GAS</p> <p>2. Name of Operator BURLINGTON RESOURCES OIL & GAS COMPANY</p> <p>3. Address & Phone No. of Operator PO Box 4289, Farmington, NM 87499 (505) 326-9700</p> <p>4. Location of Well, Footage, Sec., T, R, M 890' FSL 1140' FWL, Sec. 36, T-25-N, R-7-W, NMPM, Rio Arriba County</p> | <p>API # (assigned by OCD) 30-039-05692</p> <p>5. Lease Number</p> <p>6. State Oil&Gas Lease # E-505-5</p> <p>7. Lease Name/Unit Name Canyon Largo Unit</p> <p>8. Well No. 99</p> <p>9. Pool Name or Wildcat Ballard Pictured Cliffs</p> <p>10. Elevation:</p> |
|---|--|

| Type of Submission | Type of Action |
|--|---|
| <input checked="" type="checkbox"/> Notice of Intent | <input type="checkbox"/> Abandonment |
| <input type="checkbox"/> Subsequent Report | <input type="checkbox"/> Recompletion |
| <input type="checkbox"/> Final Abandonment | <input type="checkbox"/> Plugging Back |
| | <input type="checkbox"/> Casing Repair |
| | <input type="checkbox"/> Altering Casing |
| | <input checked="" type="checkbox"/> Other - restimulate |
| | <input type="checkbox"/> Change of Plans |
| | <input type="checkbox"/> New Construction |
| | <input type="checkbox"/> Non-Routine Fracturing |
| | <input type="checkbox"/> Water Shut off |
| | <input type="checkbox"/> Conversion to Injection |

13. Describe Proposed or Completed Operations

It is intended to restimulate the Pictured Cliffs formation of the subject well in the following manner:

Clean out to plug back total depth at 2350'. Acidize and foam fracture treat the Pictured Cliffs zone. Clean out and return well to production.

SIGNATURE  (MDW) Regulatory Administrator November 30, 1998

TLW

(This space for State Use)

ORIGINAL SIGNED BY CHARLIE T. PERRIN

DEPUTY OIL & GAS INSPECTOR, DIST. #3

DEC 4 1998

Approved by _____ Title _____ Date _____