(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

				X
NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF		X
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING		
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING		
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF REDRILLING OR REPAIR		
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT		
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY		
NOTICE OF INTENTION TO ABANDON WELL				

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

RECEIVED MAY 7 1956 U.S. GEOLOGICAL SURVEY FARMINGTON, NEW MEXICO

_____ May 4th _____, 19 56

Well No. ___7___ is located 1100 ft. from {N/S} line and 1460 ft. from {E/W} line of sec. 6

NW/4 ENE/4 Sec. 6 _____ 25N _____ 7W _____ N.M.P.M.
(¼ Sec. and Sec. No.) _____ (Twp.) _____ (Range) _____ (Meridian)

Ballard _____ Rio Arriba _____ New Mexico
(Field) _____ (County or Subdivision) _____ (State or Territory)

The elevation of the derrick floor above sea level is 6082 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

3-24-56   TD 104' RKB. Set 3 joints 94' of J-55 casing at 104' with 70 sacks circulated to surface.

3-25-56   Pressured up on casing to 500#. No pressure decrease in 35 minutes.

RECEIVED JUN 22 1956 Oil & Gas Com. DIST. 3

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company __BENSON-MONTIN__

Address __405½ West Broadway__

__Farmington, New Mexico__

By _____ (signature)

Title __Field Superintendent__