UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

Sundry Notices and Reports on Wel	ls [*]
1. Type of Well GAS	 Lease Number Jic.Cont 110 If Indian, All. or Tribe Name Jicarilla Apache Unit Agreement Name
2. Name of Operator	
Meridian Oil Inc.	8. Well Name & Number
3. Address & Phone No. of Operator PO Box 4289, Farmington, NM 87499 (505) 326-9700	Jicarilla J #8 9. API Well No.
4. Location of Well, Footage, Sec., T, R, M 990'FSL, 990'FWL Sec.19, T-26-N, R-5-W, NMPM	10. Field and Pool S.Blanco PC 11. County and State San Juan Co, NM
12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE	, REPORT, OTHER DATA
Subsequent Report Plugging Back X Casing Repair	cion Change of Plans New Construction Non-Routine Fracturing Water Shut off Conversion to Injection
13. Describe Proposed or Completed Operations	
The subject well has a suspected casing failure be It is intended to attempt repair of the clean out of the open hole section to reproduction. The failure will be isolated and squeezed as nece of 500 psi. The open hole will be cleaned out to current PBTD An 1 1/4" production tubing string will be set at schematic. DECEMBED JUN-91992 OIL CON. DIV.	production casing and turn the well to ssary to hold a minimum
	
14 I hereby certify that the foregoing is true and co	orrect.
Signed Segay Stadfuld (DB) Title Regulatory Af	fairPPROVED 6-3-92_
(This space for Federal or State Office use) APPROVED BY	
MOCD	AREA MANAGER

Jicarilla J #8 South Blanco PC SW/SW/4 Sec.19, T26N,R05W Wellbore Schematic

