


STATE OF NEW MEXICO  
OIL CONSERVATION  
COMMISSION  
DISTRICT NO. 3  
Phone 99 P. O. Box 697  
AZTEC, NEW MEXICO

(SUBMIT IN TRIPLICATE)  
UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

N.M.  
Land Office .....  
03552  
Lease No. ....  
E1/4 Sec. 22  
Unit .....

SUNDRY NOTICES AND REPORTS ON WELLS



NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

December 27, 1951

Well No. 2-30-343 is located 990 ft. from N line and 990 ft. from E line of sec. 22  
E1/4, NE/4, Sec. 22 26N 6W R.M.P.M.  
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)  
Wilcox Ello Arriba New Mexico  
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 6655 ft. OR

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Spudded 12-20-51

Cemented 10 3/4" OD casing at 574' with 200 sacks cement.  
Cement circulated.  
Shut down for Christmas.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.


Company LOWRY et al Operating Account

Address Room 219  
616 East Central Avenue  
Albuquerque, New Mexico

By Earl E. McGill  
Office Manager  
Title .....

Land Office  
License No.  
Unit

(SUBMIT IN TRIPlicate)  
UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY



SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO ABANDON WELL	
NOTICE OF INTENTION TO PULL OR ALTER CASING	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE FLUIDS	
SUBSEQUENT REPORT OF WATER SHUT-OFF	
SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
SUBSEQUENT REPORT OF ALTERING CASING	
SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
SUBSEQUENT REPORT OF ABANDONMENT	
SUPPLEMENTARY WELL HISTORY	

(INDICATE ABOVE BY CHECKING NATURE OF REPORT, NOTICE OF OTHER DATA)

Well No. \_\_\_\_\_ is located \_\_\_\_\_ ft. from \_\_\_\_\_ line and \_\_\_\_\_ ft. from \_\_\_\_\_ line of sec. \_\_\_\_\_  
(Field) (County or Subdivision) (State or Territory)  
(Section and Sec. No.) (Twp.) (Range)

The elevation of the derrick floor above sea level is \_\_\_\_\_ ft.

DETAILS OF WORK

(Give names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casing; indicate mudding jobs, cementing, etc., and all other important proposed work)

Submitted \_\_\_\_\_

Witnessed by \_\_\_\_\_  
and \_\_\_\_\_  
and \_\_\_\_\_

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Approved by \_\_\_\_\_

Company \_\_\_\_\_

Address \_\_\_\_\_

\_\_\_\_\_

By \_\_\_\_\_

\_\_\_\_\_

Title \_\_\_\_\_

\_\_\_\_\_