UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Budget Bureau No. 42-R359.4. Approval expires 12-31-60.
ndian Agency . Jeer 1118-
cont. No. 109 P.C.
Allettee
ease No 14 none 1 1

SUNDRY NOTICES AND	REPORTS ON WELLS
OTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
THE PARTY OF THE P	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
TO THE WATER SHIT OFF	SUBSEQUENT REPORT OF ALTERING CASING
TO DEDDIT OF REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR
TO SHOOT OR ACIDITE	SUBSEQUENT REPORT OF ABANDONMENT.
DTICE OF INTENTION TO PULL OR ALTER CASING.	SUPPLEMENTARY WELL HISTORY
OTICE OF INTENTION TO ABANDON WELL.	
(INDIGATE ABOVE BY CHECK MARK NATU	RE OF REPORT, NOTICE, OR OTHER DATA)
	Arril 25 , 19.61
400.007	
ell No. 14 is located 1650 ft. from	line and 1650 ft. from $\{E\}$ line of sec. 15
E Section 15	(Meridian)
(¼ Sec. and Sec. No.) (Twp.) (Ra	nge) (Meridian)
o.Blanco Pictured Cliffa Rio Arril	(State or Territory)
(Field) (County or Su	DQIARION)
ne elevation of the derrick floor above sea level	s 6614 ft.
ne elevation of the derrick noor above sea level	
DETAILS	OF WORK
	sinks, and lengths of proposed casings; indicate mudding jobs, cemen
ate names of and expected depths to objective sands; show sizes, w ing points, and all other	important proposed work)
Spudded 4-20-00.	
on h-21-61 Total Depth 107. Ren 3 joints 3 5/8" 2h6, J-95, cacing Committed with 100 sacks 171 Dismin, Stroulated to surface. Held 6008/30 to	
Committed with 100 sachs 111 Diamin, 2 Circulated to surface. Held 600/30 I understand that this plan of work must receive approval in we S1 Page Satural Cas Company Box 930 Address	APR 27 1961 Official Survey before operations may be commenced
Ran 3 joints 3 5/3 26, 3-55, casing Committed with 100 sacks 1/1 Diamin, 2 Circulated to surface. Held 600/30 I understand that this plan of work must receive approval in water than the sack of the surface of the sur	RELLIVED APR 27 1961 OIL

•