

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

| | |
|---|--|
| 1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER | 5. LEASE DESIGNATION AND SERIAL NO. NM 03554 |
| 2. NAME OF OPERATOR Caulking oil Company | 6. IF INDIAN, ALLOTTEE OR TRIBE NAME |
| 3. ADDRESS OF OPERATOR P.O. Box 780, Farmington, New Mexico 87401 | 7. UNIT AGREEMENT NAME |
| 4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1850 from the West and 1150 from the North | 8. FARM OR LEASE NAME Breech "C" |
| 14. PERMIT NO. | 9. WELL NO. 246 |
| 15. ELEVATIONS (Show whether DF, RT, GR, etc.) 6617 Gr. | 10. FIELD AND POOL, OR WILDCAT South Blanco PC |
| | 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 13 26N-6W |
| | 12. COUNTY OR PARISH Rio Arriba |
| | 13. STATE New Mexico |

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

| | | | |
|---------------------|--------------------------|----------------------|--------------------------|
| TEST WATER SHUT-OFF | <input type="checkbox"/> | PULL OR ALTER CASING | <input type="checkbox"/> |
| FRACTURE TREAT | <input type="checkbox"/> | MULTIPLE COMPLETE | <input type="checkbox"/> |
| SHOOT OR ACIDIZE | <input type="checkbox"/> | ABANDON* | <input type="checkbox"/> |
| REPAIR WELL | <input type="checkbox"/> | CHANGE PLANS | <input type="checkbox"/> |
| (Other) | | | |

SUBSEQUENT REPORT OF:

| | | | |
|-----------------------|-------------------------------------|-----------------|--------------------------|
| WATER SHUT-OFF | <input checked="" type="checkbox"/> | REPAIRING WELL | <input type="checkbox"/> |
| FRACTURE TREATMENT | <input type="checkbox"/> | ALTERING CASING | <input type="checkbox"/> |
| SHOOTING OR ACIDIZING | <input type="checkbox"/> | ABANDONMENT* | <input type="checkbox"/> |
| (Other) | | | |

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Spud 1:00 PM 5-22-77

Drilled 12 1/4" hole to 96' and cemented 8 5/8" 24# J-55 casing at 96' with 100 sacks Class B cement contouring 2% CaCl.

Plug down 3:00 PM 5-22-77. Cement circulated to surface.

5-23-77 Tested surface casing with 500# for 30 minutes. No decrease in pressure.

18. I hereby certify that the foregoing is true and correct

SIGNED E. E. Vesper

TITLE Superintendent

DATE 5-25-77

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

*See Instructions on Reverse Side