5. LEASE

UNITED STATES

DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY	Contract #117
	6. IF INDIAN, ALLOTTEE OR TRIBE NAME Jicarilla Apache
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	7. UNIT AGREEMENT NAME
reservoir. Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAME
1. oil gas other Dry Hole	9. WELL NO. #5
2. NAME OF OPERATOR	10. FIELD OR WILDCAT NAME
Consolidated Oil & Gas, Inc.	Blanco Mesaverde
3. ADDRESS OF OPERATOR Box 2038, Farmington, N.M. 87401	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	Sec. 34, T26N, R3W NMPM
below.) AT SURFACE: 790' FSL & 1850' FEL AT TOP PROD. INTERVAL:	12. COUNTY OR PARISH 13. STATE New Mexico
AT TOTAL DEPTH:	14. API NO.
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD) GL 73761
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF	
FRACTURE TREAT	
SHOOT OR ACIDIZE	(NOTE: Report results of multiple completion or zone
PULL OR ALTER CASING	change on Form 9–330.)
MULTIPLE COMPLETE	그 그 그는 그 사람들은 그래 최근 회
CHANGE ZONES	
7.57.1	
(other)	in the least give portinent dates
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly stating including estimated date of starting any proposed work. If well is measured and true vertical depths for all markers and zones pertine	ent to this work.)*
\sim	DISCUSSION OF THE PROPERTY OF
displace spotted 50 sk Dille acr	oss re peris 3970; 2000 a woo ondo
top of out 30051. Pressured up on cement pin	ig to boom, here or a second
Worked 7" csg. up to 200,000#. No free trav	et nergy 1900 .
Perf. 7" csg. @ 3750! w/4 holes. Spotted 75	Ent Way Proce 850# WOC:
Perf. 7" csg. @ 3750" W/4 hores. Spotted 75 36 sx into formation leaving top of cmt. @ 36 Shot csg. @ 1518". Did not come free. Re-s	that are @ 1442th. Could not pull.
Shot csg. d 1518'. Did not come iree. Re-s	THE COST OF THE COST OF THE PROPERTY OF THE PR
Pressured up to 1500#. Could not pump in. Shot 7" csg. @ 1370". Could not pump in @ 1	500#. Pulled & laid down 37 jts
7" 23# csg.	d not not through bridge.
Ran 2 3/8" tubing. Hit bridge @ 500". Coul Spotted 50 sx. Plug @ base of surface csg.	
Spotted 50 sx plug 1261 up to 201 WUL. Ins	stailed bry upre marker wise on brio
Subsulface Safety Valve: Marfue and Type	Set @Ft.
18. I hereby certify that the foregoing is true and correct SIGNED Prod. Supt	
Prod. Supt	t. DATE 7/19/78
SIGNED Leo Case	

(This space for Federal or State office use)