

Denny R. Funt JICARILLA APACHE TRIBE
DEPUTY OIL & GAS INSPECTOR ENVIRONMENTAL PROTECTION OFFICE

SUBMIT 1 COPY TO
NATURAL
RESOURCE DEPT
AND OIL-GAS
ADMINISTRATION

OCT 28 1997

P.O. BOX 507
DULCE, NEW MEXICO 87528

Approved
PIT REMEDIATION AND CLOSURE REPORT

Operator: PNM Gas Services (Conoco) Telephone: 324-3764
Address: 603 W. Elm Street Farmington, NM 87401
Facility or Well Name: Axi Apache K-5A #2
Location: Unit: P Sec. 10 T. 26 N. R. 5 W. County Rio Arriba
Pit Type: Separator Dehydrator X Other
Land Type: Jicarilla Apache

Pit Location: Pit dimensions: length 38' width 33' depth 8'
(Attach diagram) Reference: wellhead X other
Footage from reference: 69'
Direction from reference: Straight Degrees X East North
West of South

Depth to Ground Water:

(Vertical distance from contaminants to seasonal high water elevation or ground water)

Less than 50 feet (20 points)
50 feet to 99 feet (10 points)
Greater than 100 feet (0 points) 0

Wellhead Protection Area:

(Less than 200 feet from a private domestic water source, or, less than 1,000 feet from all other water sources)

Yes (20 points)
No (0 points) 0

Distance to Surface Water:

(Horizontal distance to perennial lakes, ponds, rivers, streams, creeks, irrigation canals and ditches)

Less than 200 feet (20 points)
200 feet to 1,000 feet (10 points)
Greater than 1,000 feet (0 points) 0

Distance to Ephemeral Stream (dry wash):

(Horizontal distance to all downgradient streams having a width of at least 10 feet)

Less than or equal to 100 feet (10 points)
Greater than 100 feet (0 points) 0

Distance to Nearest Lake, Playa, or Watering Pond:

(Horizontal distance to all downgradient lakes, playas, and livestock or wildlife water ponds)

Less than or equal to 100 feet (10 points)
Greater than 100 feet (0 points) 0

RANKING SCORE (TOTAL POINTS): 0

RECEIVED
JUL 31 1997

OIL CON. DIV.
DIST. 3

Date Remediation Started: 5/14/97 Date Completed: 7/9/97

Remediation Method: Excavation X Approx. Cubic Yards 372

(Check all appropriate sections)

Landfarmed X Amount Landfarmed (cubic yds): 372

Other _____

Remediation Location: Onsite X Offsite _____

(i.e., landfarmed on-site, name and location of off-site facility)

General Description of Remedial Action:

Removed contaminated soil from all four side walls
As to get a below 100 ppm head space reading.
Bottom of pit was solid rock.

Ground Water Encountered: No X Yes _____ Depth _____

Final Pit Closure Sampling:

Sample Location North, East, South, And West side walls

(if multiple samples, attach sample result and diagram of sample locations and depths.)

Sample depth 7'

Sample date 5/14/97 Sample time 1430

Sample Results

Soil: Benzene (ppm) ND Water: Benzene (ppb) _____

Total BTEX (ppm) ND Toluene (ppb) _____

Field headspace (ppm) 75.7 Ethylbenzene (ppb) _____

TPH ND ppm Method 8015 Total Xylenes (ppb) _____

Ground Water Sample: Yes _____ No X (If yes, attach sample results)

I HEREBY CERTIFY THAT THE INFORMATION ABOVE IS TRUE AND COMPLETE TO THE BEST OF MY KNOWLEDGE AND MY BELIEF

DATE 5/22/97 PRINTED NAME Ronald A. Dedrick






SIGNATURE Ronald A. Dedrick AND TITLE Environmental Technician II

AFTER REVIEW OF THE PIT CLOSURE INFORMATION, PIT CLOSURE IS APPROVED IN ACCORDANCE TO JICARILLA APACHE TRIBE PIT CLOSURE ORDINANCE.

APPROVED: YES X NO _____ (REASON): _____


SIGNED: Kew C Mammal DATE: 5-29-97

ixi Hprache K-017 #2
ec. 10 T26N R5W Unit P
Lonoco



4x11pache K-JH "2
Sec. 10 T26N R5W Unit P
onoco

38x33x8'



OFF: (505) 325-5667



LAB: (505) 325-1556

ANALYTICAL REPORT

Attn: *Denver Bearden*
Company: *PNM Gas Services*
Address: *603 W. Elm*
City, State: *Farmington, NM 87401*

Date: *22-May-97*
COC No.: *5461*
Sample No.: *14632*
Job No.: *2-1000*

Project Name: *PNM Gas Services - Axi Apache K-5A #2 Run 12-21*
Project Location: *9705141430; 4pt. Composite*
Sampled by: *SA* Date: *14-May-97* Time: *14:30*
Analyzed by: *HR/DC* Date: *19-May-97*
Sample Matrix: *Soil*

Laboratory Analysis

Parameter	Results as Received	Unit of Measure	Limit of Quantitation	Unit of Measure
<i>Diesel Range Organics (C10 - C28)</i>	ND	mg/kg	5.0	mg/kg

ND - Not Detected at Limit of Quantitation

Quality Assurance Report

DRO QC No.: *0519-STD*

Continuing Calibration Verification

Parameter	Method Blank	Unit of Measure	True Value	Analyzed Value	RPD	RPD Limit
<i>Diesel Range (C10 - C28)</i>	ND	ppm	100	112	11.2	15%

Matrix Spike

Parameter	1- Percent Recovered	2 - Percent Recovered	Limit	RPD	RPD Limit
<i>Diesel Range (C10-C28)</i>	100	100	(70-130)	0	20%

Method - *SW-846 EPA Method 8015A mod. - Nonhalogenated Volatile Hydrocarbons by Gas Chromatography*

Approved by: *[Signature]*
Date: *5/22/97*

OFF: (505) 325-5667



LAB: (505) 325-1556

ANALYTICAL REPORT

Attn: *Denver Bearden*
Company: *PNM Gas Services*
Address: *603 W. Elm*
City, State: *Farmington, NM 87401*

Date: *22-May-97*
COC No.: *5461*
Sample No.: *14632*
Job No.: *2-1000*

Project Name: *PNM Gas Services - Axi Apache K-5A #2 Run 12-21*

Project Location: *9705141430; 4pt. Composite*

Sampled by: *SA* Date: *14-May-97* Time: *14:30*

Analyzed by: *DC* Date: *21-May-97*

Sample Matrix: *Soil*

Laboratory Analysis

Parameter	Results as Received	Unit of Measure	Limit of Quantitation	Unit of Measure
<i>Benzene</i>	ND	ug/kg	1.0	ug/kg
<i>Toluene</i>	ND	ug/kg	1.0	ug/kg
<i>Ethylbenzene</i>	ND	ug/kg	1.0	ug/kg
<i>m,p-Xylene</i>	ND	ug/kg	1.0	ug/kg
<i>o-Xylene</i>	ND	ug/kg	1.0	ug/kg
	<i>TOTAL</i>	ND		ug/kg

ND - Not Detected at Limit of Quantitation

Method - SW-846 EPA Method 8020A Aromatic Volatile Organics by Gas Chromatography

Approved by: *[Signature]*
Date: *5/22/97*

P.O. BOX 2606 • FARMINGTON, NM 87499

- TECHNOLOGY BLENDING INDUSTRY WITH THE ENVIRONMENT -

JICARILLA APACHE TRIBE
ENVIRONMENTAL
PROTECTION OFFICE
P.O. BOX 507
DULCE, NEW MEXICO 87528

SUBMIT 1 COPY TO
NATURAL
RESOURCE DEPT
AND OIL GAS
ADMINISTRATION

ON-SITE SOIL REMEDIATION REPORT

Operator: PNM Gas Services (Conoco) Telephone: 324-3764
Address: 603 W. Elm Street Farmington, NM 87401
Facility or Well Name: Axi Apache K-SA #2
Location: Unit: P Sec. 10 T. 26 N. R. 5 W. County Rio Arriba
Land Type: Jicarilla Apache

Date Remediation Started: 5/14/97 Date Completed: ~~372~~ 6/12/97
Remediation Method: Landfilled X Approx. cubic yards 372
Composted —
Other —

Depth to Ground Water: (pts.) 0
Distance to an Ephemeral Stream: (pts.) 0
Distance to Nearest Lake, Playa,
or Watering Pond: (pts.) 0
Wellhead Protection Area: (pts.) 0
Distance to Surface Water: (pts.) 0
Ranking Score (Total Points): 0

Final Closure Sampling:

Sampling Date: 6/4/97 Time 1046
Sampling Results:
Field Headspace (ppm) 50.3
TPH (ppm) 89 Method 8015
Other —

I HEREBY CERTIFY THAT THE INFORMATION ABOVE IS TRUE AND COMPLETE TO THE BEST OF MY KNOWLEDGE AND BELIEF


DATE 6/12/97 PRINTED NAME Ronald A. Dedrick
SIGNATURE Ronald A. Dedrick AND TITLE Environmental Technician II

AFTER REVIEW OF THE SOIL REMEDIATION INFORMATION, ON-SITE REMEDIATION APPROVED IN ACCORDANCE TO THE
JICARILLA APACHE TRIBE PIT CLOSURE ORDINANCE

APPROVED: YES X NO — (REASON) OK for Backfill
SIGNED: Kevin Mammill DATE: 6-16-97

Xiltpache K-5H #2
Sec. 10 T26N R5W Unit P
07000

Land farm



OFF: (505) 325-5667



LAB: (505) 325-1556

ANALYTICAL REPORT

Attn: **Denver Bearden**
Company: **PNM Gas Services**
Address: **603 W. Elm**
City, State: **Farmington, NM 87401**

Date: **9-Jun-97**
COC No.: **5484**
Sample No.: **14850**
Job No.: **2-1000**

Project Name: **PNM Gas Services - Axi Apache K-5A #2 Landfarm**
Project Location: **9706041046; 5pt. Composite**
Sampled by: **RB** Date: **4-Jun-97** Time: **10:46**
Analyzed by: **DC/HR** Date: **5-Jun-97**
Sample Matrix: **Soil**

Laboratory Analysis

Parameter	Results as Received	Unit of Measure	Limit of Quantitation	Unit of Measure
Diesel Range Organics (C10 - C28)	89	mg/kg	5	mg/kg

ND - Not Detected at Limit of Quantitation

Quality Assurance Report

DRO QC No.: 0548-STD

Continuing Calibration Verification

Parameter	Method Blank	Unit of Measure	True Value	Analyzed Value	RPD	RPD Limit
Diesel Range (C10 - C28)	ND	ppm	200	182	9.5	15%

Matrix Spike

Parameter	1- Percent Recovered	2 - Percent Recovered	Limit	RPD	RPD Limit
Diesel Range (C10-C28)	88	84	(70-130)	5	20%

Method - SW-846 EPA Method 8015A mod. - Nonhalogenated Volatile Hydrocarbons by Gas Chromatography

Approved by: 
Date: **6/9/97**