


MERRION OIL & GAS CORPORATION

Canyon Largo Unit 315
Sec. 28, T25N, R6W
Rio Arriba County, New Mexico

SLOPE TESTS

<u>Depth</u>	<u>Hole Deviation</u>
1638'	3/4°
2630'	2 °
4783'	1-1/2°



State of New Mexico)
) ss
 County of San Juan)

I, Steve S. Dunn, being first duly sworn, depose and state that the above and foregoing depth and hole deviation figures are true and correct to the best of my information and belief.

Subscribed and sworn before me this 9th day of December, 1982

Steve S. Dunn

[Signature]
 Notary Public

My Commission Expires Dec 11, 1984