UNITED STATES DEPARTMENT OF THE INTERIOR **GEOLOGICAL SURVEY**

·	
Form 9–331 Dec. 1973	Form Approved. Budget Bureau No. 42–R1424
UNITED STATES	5. LEASE
DEPARTMENT OF THE INTERIOR	NM 03553
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different	7. UNIT AGREEMENT NAME
reservoir. Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAME Breech D
1. oil gas	9. WELL NO.
2. NAME OF OPERATOR	140
Caulkins Oil Company	10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR	Blanco Mesa Verde
P.O. Box 780 Farmington, New Mexico	11. SEC., T., R., M., OR BLK. AND SURVEY OR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	AREA
below.)	Section 11 26 North 6 West
AT SURFACE: 990' from North and 990' from Ea	1
AT TOP PROD. INTERVAL: Same AT TOTAL DEPTH: Same	Rio Arriba New Mexico
	14. API NO.
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)
TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL PULL OR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES ABANDON* (other) Regarding delinquint report NIII 2B appli 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is directly measured and true vertical depths for all markers and zones pertinent Well completed ready to produce 8-23-8 Well has been shut in waiting on pipel Gas Company of New Mexico report connections	(NOTE: Report results of multiple completion or zone change on Form 9–330.) PRVEY M. Cation The all pertinent details, and give pertinent dates lirectionally drilled, give subsurface locations and to this work.)* 12. Line connection to date
Subsurface Safety Valve: Manu. and Type	SetF
18. I hereby certify that the foregoing is true and correct	

REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD) 6600 KB
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL PULL OR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES ABANDON* (other) Regarding delinquint report NII ZB appli	(NOTE: Report results of multiple completion or zone change on Form 9–330.)
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly statincluding estimated date of starting any proposed work. If well is dimeasured and true vertical depths for all markers and zones pertinent	irectionally drilled, give subsurface locations and
Well completed ready to produce 8-23-8	2.
Well has been shut in waiting on pipel	ine connection.to date
Gas Company of New Mexico report conne	Q OCI SELLI
Subsurface Safety Valve: Manu. and Type	Set Ft
18. I hereby certify that the foregoing is true and correct SIGNED Superinte Superinte	ndent DATE10-12-82
(This space for Federal or State of	fice use)
APPROVED BY LIGHTLES FOR PECORDTITLE CONDITIONS OF APPROVAL, IF ANY:	DATE
OCT 2.0 1982	

*See Instructions on Reverse Side