

(SUBMIT IN TRIPLICATE)

Indian Agency Navajo Allotment

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Allottee Window Rock  
Lease No. 11-30-603-1370

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Navajo Allotment September 3, 1959

Well No. 1 is located 990 ft. from N line and 660 ft. from E line of sec. 30  
SR/4 Sec. 30 25N 10W N.M.P.M.  
 (1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)  
Moti Lower Gallup San Juan New Mexico  
 (Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 6712 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

This well was sand fractured with 20000 gal. Lease Grade & 20000/ S4. - in the Lower Pay thru perfor 5206 - 5209. After recovering Load Oil the well flowed 169 BOPD - 6-23-59



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company SUNRAY MID-CONTINENT OIL COMPANY  
 Address Rm. 166  
Petroleum Center Building  
Farmington, New Mexico  
 By Edm. Stensurek  
 Title Engineer

