

STATE OF NEW MEXICO
OIL CONSERVATION
COMMISSION
DISTRICT NO. 3
Phone 99 P. O. Box 697
AZTEC, NEW MEXICO

(SUBMIT IN TRIPLICATE)
UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe
Lease No. 078154
Unit Federal Ross

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	XX
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)


December 15, 1955
Federal Ross
Well No. 1 is located 790 ft. from N line and 790 ft. from W line of sec. 25
NW/4 Sec. 25 25N 13W M.M. Principal
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Wildcat San Juan New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 6393 ft. K.B.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

- 11-8-55 Reached total depth of 1401, completed logs and shut down for orders.
11-10-55 Spotted 50 sack cement plug from 1300' to 1160', 25 sack cement plug to bottom of surface casing, 10 sack cement plug in top of surface casing, erected marker and abandoned location.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company The British-American Oil Producing Company

Address P. O. Box 180

Denver, Colorado


By

Thomas M. Hogan

Title District Superintendent

Land Office _____
 Serial No. 078154
 Date Federal 1922

**DEPARTMENT OF THE INTERIOR
 GEOLOGICAL SURVEY
 UNITED STATES
 (SUBMIT IN REPLICATES)**



SUNDRY NOTICES AND REPORTS ON WELLS

CONSEQUENT REPORT OF WATER SHUT-OFF	REPORT OF INTENTION TO DRILL
CONSEQUENT REPORT OF SHOOTING OR ACIDIZING	REPORT OF INTENTION TO CHANGE PLANS
CONSEQUENT REPORT OF ALTERING CASING	REPORT OF INTENTION TO TEST WATER SHUT-OFF
CONSEQUENT REPORT OF REPAIRING OR REPAIR	REPORT OF INTENTION TO RE-DRILL OR REPAIR WELL
CONSEQUENT REPORT OF ABANDONMENT	REPORT OF INTENTION TO SHUT OR ACIDIZE
CONSEQUENT REPORT OF ABANDONMENT	REPORT OF INTENTION TO TULL OR ALTER CASING
CONSEQUENT REPORT OF ABANDONMENT	REPORT OF INTENTION TO ABANDON WELL

(INDICATE ABOVE BY CHECKING (X) IN COLUMN OF REPORT, NOTICE, OR OTHER DATA)

Federal 1922

_____ is located _____ ft. from _____ line of sec. 25
 _____ line and _____ line and _____ line
 _____ line of sec. 25

San Juan
 (County or Subdivision)

New Mexico
 (State or Territory)

The elevation of the bench floor above sea level is 6393 ft. A.S.

DETAILS OF WORK

11-2-22 Reached total depth of 1401, completed logs and shut down for
 orders.
 11-10-22 Spotted 20 sack cement plug from 1300' to 1100', 25 sack cement
 plug to bottom of surface casing, 10 sack cement plug in top of
 surface casing, erected water and abandoned location.

I understand that this plan of work must receive approval of the Geological Survey before operations may be commenced.

Company The British-American Oil Producing Company
 Address P. O. Box 180
 Denver, Colorado

By _____
 Thomas M. Hogan
 Title District Superintendent

GEOLOGICAL COMPLETION REPORT FOR
BRITISH-AMERICAN #1 FEDERAL-ROSS

Well Classification:

Wildcat, Farmington area
San Juan County, New Mexico
British-American #1 Federal-Ross
790' FNL & 790' FWL section 25-25N-13W

Well Data:

Commenced Drilling:	November 5, 1955
Completed Drilling:	November 8, 1955
Contractor:	Banner Drilling Company
Casing Record:	9-5/8" at 122 w/90 sax
Elevation:	6393' KB
Total Depth and Datum:	1401 (+4992) KB

Completion Data:

Plugged and abandoned:	November 10, 1955
	50 sax 1300-1160
	25 sax in surface casing
	10 sax in top of surface casing



Geological Data:

Logging Data:

Samples:	Samples stored in Farmington, New Mexico
Electric log:	124-1401
Expanded E.S.:	200-1401
Microlog:	Not run because of bad hole conditions.

Formation Record:

	<u>Sample Top</u>	<u>Schl. Top</u>	<u>Schl. Datum</u>	<u>Fluid</u>
Pictured Cliffs ss	1228	1192	+5201	salt water
Lewis sh		1374	+5019	

Core Record:

No cores

Drill Stem Test Record:

DST #1 1218-1401 (TD)	Pictured Cliffs. Open 60 minutes, shut in 60 minutes. Immediate weak blow, died in 16 minutes. Recovered 30 feet mud, 450 feet salty water. IFP 85#, FFP 175#, SIEHP 325#, IHP 760#, FHP 695#.
-----------------------	---