

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

Mims No. 1 SF 078067

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

Carson Unit

8. FARM OR LEASE NAME

9. WELL NO.

43-23

10. FIELD AND POOL, OR WILDCAT

Bisti

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Section 23-T25N-R12W

12. COUNTY OR PARISH

San Juan

13. STATE

New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ Water Injector

2. NAME OF OPERATOR
Shell Oil Company

3. ADDRESS OF OPERATOR
1700 Broadway, Denver, Colorado 80202

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

3300' FNL & 660' FEL Section 23

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, CR, etc.)

6418' KB

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other) ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON* ☐

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) ☐

REPAIRING WELL ☐


ALTERING CASING ☐

ABANDONMENT* ☒

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

See attachment



NOV 6 1976

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Div. Opers. Engr.

DATE 11/4/75

(This space for Federal or State office use)

APPROVED

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL IF ANY:

NOV 11 1976

M. L. SEELINGER
DISTRICT ENGINEER

*See Instructions on Reverse Side

WELL PLUGGED AND ABANDONED

SHELL OIL COMPANY

FROM: 9/29 - 10/7/75

LEASE

CARSON UNIT

DIVISION

WESTERN

COUNTY

SAN JUAN

WELL NO.

BISTI

43-23 WI

ELEV

6418 KB

STATE

NEW MEXICO

NEW MEXICOBISTI FIELD

Carson Unit 43-23 WI

"FR" TD 4945. Prep to P&A. MI&RU Farmington Well Service to pull pkr. Attempted to bleed off wellhead. Well blw'g gas & oil. SI for night. 9/27 Well SI; 200# tbg press. Blew well to pit & brought off wellhead press. Attempted to remove slip type wellhead donut w/tension pkr in hole & couldn't. SI well. SEP 29 1975

Carson Unit 43-23 WI

TD 4945. Pulled tbg up & set slips. Filled annulus w/wtr. Released pkr. Pulled 152 jts 2-3/8 tbg. Removed pkr & ran back in hole w/2-3/8 tbg. Tagged btm @ 4870. Pulled 2 jts & SI well. (RDUFA) SEP 30 1975

Carson Unit 43-23 WI

TD 4945. (RRD 9/30/75) MI&RU Sigoro. Circ'd hole clean. Mixed & circ'd 15 sx mud. Mixed & spt'd 20 sx cmt on btm. Est top of cmt 4650. Pulled & LD 2-3/8 tbg. MI&RU csg jacks & SD for night. 10/4 PU on csg to remove slips & csg parted. Attempted to screw csg back in; could not. RU & pulled 256' csg. Removed bad jt & ran back in hole w/4-1/2 csg & screwed into csg stub. Stretched & worked pipe. Had approx 1150' free. SD for weekend. OCT 08 1975

Carson Unit 43-23 WI

TD 4945. Worked csg; unable to work loose below 1135'. Ran in to shoot off csg; could not shoot below 845'. Shot csg off @ 820'. Pulled up 10' & spt'd 50 sx cmt plug from 820-600'. Pulled up to 330' & spt'd 55 sx plug from 330-70'. Pulled remainder 4-1/2" csg & spt'd 10 sx plug in csg @ surface & installed permanent abandonment marker. Recovered 820' of 4-1/2" csg. Well P&A. FINAL REPORT OCT 07 1975