

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		5. LEASE DESIGNATION AND SERIAL NO. Mims No. 1 SF078067	
2. NAME OF OPERATOR Shell Oil Company		6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
3. ADDRESS OF OPERATOR 1700 Broadway, Denver, Colorado 80290		7. UNIT AGREEMENT NAME Carson Unit	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1890' FNL & 616' FEL Section 23		8. FARM OR LEASE NAME Unit	
14. PERMIT NO.		9. WELL NO. 42-23	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 6341 KB		10. FIELD AND POOL, OR WILDCAT Bisti	
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Section 23-T25N-R12W	
		12. COUNTY OR PARISH San Juan	13. STATE N.M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
(Other) <input type="checkbox"/>	

SUBSEQUENT REPORT OF:

WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input checked="" type="checkbox"/>
(Other) <input type="checkbox"/>	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

See attachment

WILL SEND FINAL SUNDRY WHEN LOCATION
CLEANED AND READY FOR INSPECTION

18. I hereby certify that the foregoing is true and correct

SIGNED

L. P. Plauty

TITLE

Div. Ops. Engr.

DATE

SEP 27 1977

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

cc: NMO&GCC

*See Instructions on Reverse Side

PLUG & ABANDON

SHELL OIL COMPANY

FROM: 9/1-6/77

LEASE	CARSON UNIT	WELL NO.	BISTI
DIVISION	WESTERN	ELEV	42-23
COUNTY	SAN JUAN	STATE	6341 KB
			NEW MEXICO

NEW MEXICO
BISTI FIELD

Carson Unit 42-23
(P&A)

"FR" TD 4940. PB 4920. AFE #529706 provides funds to plug & abandon well. 8/29 RU Bedford. LD tbg. 8/30 Ran 2-3/8 tbg to PB. Spt'd 20 sx cmt across Gallup perms. Pulled 50 jts. 8/31 RU jacks & shot csg @ 1182. Spt'd 50 sx across stub - Pictured Cliffs & Fruitland Coal. Pulled to 330.

SEP 01 1977

Carson Unit 42-23
(P&A)

TD 4940. PB 4920. No report.

SEP 02 1977

Carson Unit 42-23
(P&A)

TD 4940. PB 4920. 8/31 Fin'd pull'g tbg. RU hyd jacks. Shot csg @ 1182 & spt'd 50 sx cmt plug across csg stub - Pictured Cliffs & Fruitland Coal. Pulled csg to 330' & spt'd 35 sx cmt across Ojo Alamo Sd. Pulled csg to 174' & spt'd 25 sx across shoe of sfc csg. Pulled csg out of hole. Spt'd 10 sx on sfc & installed abandonment marker. RD Bedford.
FINAL REPORT

SEP 06 1977