

			X
	21		

(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office Santa Fe, N.M.  
Lease No. 3F 078065  
Unit \_\_\_\_\_

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	X
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Gov't. \_\_\_\_\_  
Well No. 41-21 is located 660 ft. from N line and 660 ft. from E line of sec. 21  
NE 21 (1/4 Sec. and Sec. No.)  
Bisti (Field)  
25N (Twp.) 12W (Range) N11W (Meridian)  
San Juan (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is 6255 ft. (Approx. Ground)

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

(Spudded 10-23-57)

10-23, 24-57 Ran and cemented 8-5/8" 24#, J-55 casing at 118' with 100 sacks treated cement. Good returns to surface but dropped 15', recemented on outside with 10 sacks cement. Flanged up and waited on cement. Tested BOP and casing with 700 PSI 15 minutes, O.K.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Shell Oil Company  
Address 101 South Behrend  
Farmington, New Mexico  
By BW Shepard  
B. W. Shepard  
Title Exploitation Engineer