

	X		
	2		

(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office Santa Fe, N.M.

Lease No. SF-C78061

Unit Carson Unit

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	X
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

July 7, 19 61

water well  
Well No. 3-4 is located 44.6 ft. from N line and 2105.2 ft. from W line of sec. 20


NE 1/4 Sec. 20 T. 25 N., R. 11 W. N.M.  
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)  
Bisti San Juan New Mexico  
(Field) (County or Subdivision) (State or Territory)

Kelly Dushing  
The elevation of the ~~casings~~ above sea level is 6418 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

7-1-61 Ran and cemented 7", J-55, 23# casing @ 3047' (3850 TD) with 275 ex. cement treated with 20% Diacel D and 2% calcium chloride. Flanged up. Tested casing with 1500 psi. OK.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Shell Oil Company

Address P.O. Box 120

Farlington, New Mexico

Original Signed By  
W. M. Marshall  
By W. M. Marshall  
Title Division Exploitation Engineer