

(SUBMIT IN TRIPLICATE)

Indian Agency Navajo

	18		
X			

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Allottee Allotted Lands

Lease No. 14-20-603-1285

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	X
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL		SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	X
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

January 27, 1960

Carson Unit

Well No. 13-18 is located 1980 ft. from S line and 750 ft. from W line of sec. 18

NW SW 18
(1/4 Sec. and Sec. No.)

25N
(Twp.)

11W
(Range)

N.M.P.M.
(Meridian)

Bisti
(Field)

San Juan
(County or Subdivision)

New Mexico
(State or Territory)

Kelly Bushing

The elevation of the ~~drill floor~~ above sea level is 6395 ft.

RECEIVED

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Spudded 1-11-60

- 1-11-60 Ran and cemented (100') 8-5/8", 28#, J-55 casing at 109' with 100
to sacks, 120 cu. ft. Portland cement treated with 2% calcium chloride.
1-12-60 Surface temperature 20°F+. Formation temperature 75°F+. Estimated
strength of cement after 12 hours 1000 psi. Flanged up. Pressure
tested casing and BOP with 700 psi, OK.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Shall Oil Company

Address Post Office Box 158

Farmington, New Mexico

By M. W. McGarry, Jr.

Title Exploitation Engineer

