


(Feb. 1951)



(SUBMIT IN TRIPPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Budget Bureau No. 42-R388.4  
Approval expires 12-31-60.

Land Office Santa Fe, N. M.  
Lease No. SP 078367  
Unit Garwood

# SUNDRY NOTICES AND REPORTS ON WELLS

- NOTICE OF INTENTION TO DRILL  
 NOTICE OF INTENTION TO CHANGE PLANS  
 NOTICE OF INTENTION TO TEST WATER SHUT-OFF  
 NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL  
 NOTICE OF INTENTION TO SHOOT OR ACIDIZE  
 NOTICE OF INTENTION TO PULL OR ALTER CASING  
 NOTICE OF INTENTION TO ABANDON WELL

- SUBSEQUENT REPORT OF WATER SHUT-OFF  
 SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING  
 SUBSEQUENT REPORT OF ALTERING CASING  
 SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR  
 SUBSEQUENT REPORT OF ABANDONMENT  
 SUPPLEMENTARY WELL HISTORY

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Garwood Unit

Well No. 41-14 is located 660 ft. from [N] line and 660 ft. from [E] line of sec. 14, 19 57

NE/4 SE/4 SW/4 14  
(Sec. and Sec. No.)

25W  
(Twp.)

12N  
(Range)

WMPH  
(Meridian)

Santa Fe  
(County or Subdivision)

New Mexico  
(State or Territory)

MAY 13 1957

RECEIVED  
OIL CONS. CO.,  
DIST. 3

The elevation of the well is 6372 ft. (approx. ground)

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, etc.)

## DETAILS OF WORK

1. Drill 12-1/4" hole to 200' ±.
2. Run and cement 5-5/8" casing at 200' ± with 100 sacks construction cement.
3. Drill 7-7/8" hole to total depth of 5065' (Gallup).
4. A supplementary notice will be issued prior to completion.

Surface formation is upper Cretaceous

understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

pany

SHELL OIL COMPANY

108 North Railroad Avenue  
Durango, New Mexico

By


R. W. Shepard

Title

R. W. Shepard  
Exploration Engineer

16-8437-6





**REFERENCE POINT DATUM—**

1"x2" stakes set at 10' N.S.E. & W. of Loc.      ◎ = G.L.O. BRASS CAP FOUND  
 1"x2" hubs & 3' flag set at 150' N., S., E., & W. of Loc.  
 1"x2" hub & 8' flag set at Loc. being 660' S. & 660' W.  
 from the NE cor. of Sec. 14, T.25N., R. 12W. N.M.P.M.  
 1"x2" hub and 3' flag bears S.45°E. a distance of 298' from  
 the Loc. for B.M.

This is to certify that the above plat was prepared  
 from field notes of an actual survey made by me on  
 March 31, 1957, and that the same is true and correct  
 to the best of my knowledge and belief.

April 2, 1957

*John A. Kroeger*  
 John A. Kroeger - Reg. Land Surveyor  
 N.M. Reg. No. 1941

Drawn By: A.C.T.	SHELL OIL COMPANY	Scale 1"=1000'
Checked By: <i>JAK</i>		Z 20-413
Date: 4-1-57		

LOCATION OF CARSON UNIT 41-14  
 SAN JUAN COUNTY, N.M., SEC. 14, T.25N., R.12W., N.M.P.M.

