

			X
	14		

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe, N. M.
Lease No. SP 078067
Unit Carson

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	X
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

June 20, 19 57

Carson Unit

Well No. 41-14 is located 660 ft. from [N] line and 660 ft. from [E] line of sec. 14
NE NE 14 25N 12W 1041M
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)

Bisti

(Field)

San Juan

(County or Subdivision)

New Mexico

(State or Territory)

Kelly Dushing

The elevation of the ~~surface~~ above sea level is 6383 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

(Spudded 5-23-57)

5-23, 24-57

Ran and cemented 200' 8-5/8", 24", casing at 210' with 130 sacks construction cement. Good cement returns to surface. Flanged up and waited on cement. Pressure tested BOP and casing with 700 psi. for 15 minutes, ok.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations are commenced.

Company Shell Oil Company
Address 108 North Behrend Avenue
Farmington, New Mexico

By B. W. Shepard
E. W. Shepard
Title Exploitation Engineer



