

(SUBMIT IN TRIPLICATE)

Land Office Santa Fe, N. M.

Lease No. ST 078066

Unit _____

	X	
	15	

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	X
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

August 12, 1957, 19__

Gov't.

Well No. 21-15 is located 660 ft. from N line and 2109.34 ft. from E line of sec. 15.

15
(1/4 Sec. and Sec. No.)

25N
(Twp.)

12E
(Range)

RMN
(Meridian)

Hindi
(Field)

San Juan
(County or Subdivision)

N. Mex.
(State or Territory)

The elevation ~~of the derrick floor above sea level~~ is 6250 ft. (approx. ground).

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

(Spudied 8-10-57)

8-9, 10-57 Ran and cemented 3-5/8" 24#, J-55 casing at 117' with 85 sac treated cement. Good returns to surface. Flanged up and united on cement. Pressure tested. B.O.P. and casing with 700 psi for 15 min. OK.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Shell Oil Company

Address 101 E. Behrend

Farmington, New Mexico

By B. W. Shepard

Title Exploitation Engineer