Form 9-331 (May 1963)

SUBMIT IN TRIPLICATE* UNITED STATES

DATE ___

DE	PARTMENT OF THE INTERIOR GEOLOGICAL SURVEY	OR verse side)	5. LEASE DESIGNATION AND SERIAL NO. L. M. Phillips No. 1 SF 078063
	NOTICES AND REPORTS C		6. IF INDIAN, ALLOTTEE OR TRIBE NAME
1. OIL X GAS WELL X WELL	7. UNIT AGREEMENT NAME		
2. NAME OF OPERATOR	Carson Unit 8. FARM OR LEASE NAME		
Shell Oil Company			Unit
3. ADDRESS OF OPERATOR	9. WELL NO.		
1700 Broadway, Der	34-7		
4. LOCATION OF WELL (Report See also space 17 below.) At surface	10. FIELD AND POOL, OR WILDCAT Bisti		
660' FSL & 1980' 1	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Section 7-T25N-R11W		
14. PERMIT NO.	15. ELEVATIONS (Show whether DF,	RT, GR, etc.)	12. COUNTY OR PARISH 13. STATE
	6385.5' KB		San Juan N.M.
16. C	heck Appropriate Box To Indicate N	ature of Notice, Report, or	
NOTICE	QUENT REPORT OF:		
TEST WATER SHUT-OFF	PULL OR ALTER CASING	WATER SHUT-OFF	REPAIRING WELL
FRACTURE TREAT	MULTIPLE COMPLETE	FRACTURE TREATMENT	ALTERING CASING
SHOOT OR ACIDIZE	ABANDON*	SHOOTING OR ACIDIZING	ABANDONMENT* X
REPAIR WELL	CHANGE PLANS	(Other)	
(Other)		(Note: Report result Completion or Recom	s of multiple completion on Well pletion Report and Log form.)
proposed work. If well nent to this work.) •	PLETED OPERATIONS (Clearly state all pertinent is directionally drilled, give subsurface locat	ions and measŭred ând true vertl	cal depths for all markers and zones perti-
	See attachmer	nt	
CLEANED AND READY		The same of the sa	SEP CON. COM. OIL CON. 3
	gregoing is true and correct	Div. Opers. Engr.	DATE SEP 2 7 1977

APPROVED BY ______CONDITIONS OF APPROVAL, IF ANY: cc: NMO&GCC

(This space for Federal or State office use)

PLUG & ABANDON SHELL OIL COMPANY		·	DI Cmy
FROM: 8/1-5/77	LEASE CARSON UNIT DIVISION WESTERN COUNTY SAN JUAN	WELL NO. ELEV STATE	BISTI 34-7 6385.5 KB NEW MEXICO
NEW MEXICO BISTI FIELD Carson Unit 34-7 (P&A)	"FR" TD 5080. PB 5063. AFE plug & abandon well. 7/30 RU to 500 psi. Pulled & LD 82 3/pmp. Circ'd hole w/mud.	#529636 provi Bedford. Pre 4" rods, 110	des funds to ss'd pmp & tbg 5/8" rods & AUG 01 1977
Carson Unit 34-7 (P&A)	TD 5080. PB 5063. Lowered th w/mud. Spt'd 20 sx cmt plug a	g to PBTD & ci	irc'd hole

TD 5080. PB 5063. Lowered the to PBTD & circ'd hole w/mud. Spt'd 20 sx cmt plug across & above perfs. Pulled & LD the. RU hyd jacks.

Carson Unit 34-7 (P&A)

TD 5080. PB 5063. 8/2 Shot 4-1/2 csg @ 1490 & spt'd 50 sx cmt plug over csg stub & Fruitland Coal. Pulled csg to 470 & spt'd 35 sx cmt plug across Ojo Alamo. Pulled csg to 175 & spt'd 25 sx cmt plug across stub of 8-5/8 sfc csg.

Carson Unit 34-7 (P&A)

TD 5080. PB 5063. No report.

AUG 04 1977

Carson Unit 34-7 (P&A)

TD 5080. PB 5063. 8/3 Placed 10 sx cmt plug to sfc.

RD Bedford & installed abandonment marker.

FINAL REPORT

AUG 05 1977