Form 9-331 (May 1963)	UNITED STATES SUBMIT IN TRIPE DEPARTMENT OF THE INTERIOR (Other instructions verse side) GEOLOGICAL SURVEY	5. LEASE DESIGNATION AND SERIAL NO. Mims No. 1
SUN (Do not use this	DRY NOTICES AND REPORTS ON WELLS form for proposals to drill or to deepen or plug back to a different reservoluse "APPLICATION FOR PERMIT—" for such proposals.)	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
OIL GAS WELL WELL	OTHER Water Injection Well	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR	Carson Unit 8. FARM OR LEASE NAME	
Shell Oil Com		
3. ADDRESS OF OPERATOR	9. WELL NO.	
1700 Broadway 4. LOCATION OF WELL (R See also space 17 belo At surface	24-11 10. FIELD AND POOL, OR WILDCAT	
660' FSL & 19	Bisti 11. SEC., T., E., M., OR BLK. AND SURVEY OR AREA Section 11-T25N-R12W	
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.)	12. COUNTY OR PARISH 13. STATE
	6265 KB	San Juan N.M.
16.	Check Appropriate Box To Indicate Nature of Notice, Repo	
S	NOTICE OF INTENTION TO:	
TEST WATER SHUT-OF		SUBSEQUENT REPORT OF:
FRACTURE TREAT	WATER SHOT-OFF	REPAIRING WELL
SHOOT OR ACIDIZE	ABANDON* FRACTURE TREATMEN SHOOTING OR ACIDIZ.	
REPAIR WELL	CHANGE PLANS (Other)	ABANDONNENT
(Other)	(Note: Report	results of multiple completion on Well Recompletion Report and Log form.)
	See attachment	OCT 71977 OIL CON. COM. DIST. 3
CLEANED AND RI 8. I hereby certify that the signed	AL SUNDRY WHEN LOCATION EADY FOR INSPECTION TITLE Div. Opers. Engr	DATE 10/5/77
(This space for Federa	al or State office use)	
APPROVED BYCONDITIONS OF API	PROVAL, IF ANY:	DATE

cc: NMO&GCC

PLUG AND ABANDON				BISTI
SHELL OIL COMPANY	LEASE	CARSON UNIT	WELL NO.	24-11
	DIVISION	WESTERN	ELEV	6265 KB
FROM: 9/12-15/77	COUNTY	SAN JUAN	STATE	NEW MEXICO

NEW MEXICO
BISTI FIELD
Carson Unit 24-11
(P&A)

"FR" TD 4925. PB 4806. AFE #529606 provides funds to plug & abandon well. 9/9 RU Bedford & pulled tbg. Ran 60 jts workstring in hole.

SEP 1 2 1977

Carson Unit 24-11 (P&A)

TD 4925. PB 4806. No report.

SEP 1 3 1977

Carson Unit 24-11 (P&A)

TD 4925. PB 4806. No report. SEP 1 4 1977

Carson Unit 24-11 (P&A)

TD 4925. PB 4806. 9/10 Fin'd run'g tbg to PBTD. Spt'd 25 sx cmt plug across & above Gallup perfs. Pulled tbg out of hole. 9/12 Set csg jacks & got rained out rest of day. 9/13 Shot csg @ 1180 & spt'd 50 sx cmt plug across csg stub (Pictured Cliffs & Fruitland Coal). Pulled csg to 180' & spt'd 35 sx cmt plug across Ojo Alamo Sd & sfc csg stub. Pulled csg out of hole. Placed 10 sx cmt plug @ sfc. Set abandonment marker & RD Bedford. SEP 1 5 1977 FINAL REPORT