



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe, New Mex.
Lease No. SF 078063
Unit _____

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	<input checked="" type="checkbox"/>	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			
<u>Notice of Intention to Complete Well</u>			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

September 7, 1956

Well No. 3 is located 1813 ft. from S line and 520 ft. from W line of sec. 7

NW 34 7 (1/4 Sec. and Sec. No.) 25N (Twp.) 11W (Range) N. M. P. M. (Meridian)
Hatch (Field) San Juan (County or Subdivision) New Mexico (State or Territory)

The elevation of the Kelly Bunking derrick floor above sea level is 6317 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate casing cementing points, and all other important proposed work)

Status: Total Depth: 5002'
Surface Casing: 8-5/8" @ 226'
Hole Size: 7-7/8" from 226' to Total Depth.

Proposed Work

1. Run and cement 5-1/2" casing at 5002' with 200 sacks cement
2. Clean out to 4980'
3. Perforate four 1/2" jet holes/ft. intervals 4890-4900 and 4939-4967.
4. Seal Oil fracture with 30,000 gals. crude oil and 60,000# sand.
5. Make production test, shut in well.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Shell Oil Company

Address 33 Richards Street

Salt Lake City, Utah

By B. W. Shepard

Title Exploitation Engineer

