

9-331b
1 1952)

(SUBMIT IN TRIPLICATE)

Indian Agency _____

Navajo Tribal

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Allottee _____

Lease No. I-119-Ind-9239

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Stanolind Gulf Navajo

Farmington, New Mexico April 5, 1957

Well No. 1 is located 415 ft. from N line and 240 ft. from E line of sec. 4

nm/4 Section 4 T-25-N R-16-W NM
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)

Wildcat San Juan New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 5473 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

On March 12, 1957, 7-5/8" casing was set at 5810' with 1000 sacks cement. After waiting on cement for 24 hours casing and water shut off were tested with 2000 pounds pressure for 30 minutes with no drop in pressure. Drilling operations were resumed.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations are commenced.

Company Pan American Petroleum Corporation

Address Box 487
Farmington, New Mexico

By L. D. Sawyer

Title Field Superintendent



