

(November 1983)
(Formerly 9-331)

DEPARTMENT OF THE INTERIOR (Other Instructions on reverse side)
BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐		2. NAME OF OPERATOR CHAMPLIN PETROLEUM COMPANY		3. ADDRESS OF OPERATOR 420 HENRY FORD AVENUE, WILMINGTON, CA. 90744-6797		4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface NWSE (1980' FSL & 1980' FEL)		5. ELEVATIONS (Show whether OF, RT, OR, etc.) 6488'GR, 6498'KB		6. PERMIT NO. APPROVED 8-15-84		7. UNIT COMMENTS NAME		8. FARM OR LEASE NAME FEDERAL 33-29		9. WELL NO. #1		10. FIELD AND POOL, OR WILDCAT BISTI-GALLUP		11. SEC., T., R., N., OR S.E. AND SUBST. OR ASSN. SEC. 29-T25N-R11W		12. COUNTY OR PARISH SAN JUAN		13. STATE NEW MEXICO	
--	--	---	--	---	--	--	--	---	--	-----------------------------------	--	-----------------------	--	--	--	-------------------	--	--	--	---	--	----------------------------------	--	-------------------------	--

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:				SUBSEQUENT REPORT OF:			
TEST WATER SHUT-OFF	☐	FILL OR ALTER CASING	☐	WATER SHUT-OFF	☐	REPAIRING WELL	☐
FRACTURE TREAT	☐	MULTIPLE COMPLETS	☐	FRACTURE TREATMENT	☐	ALTERING CASING	☐
SHOOT OR ACIDISE	☐	ABANDON*	☐	SHOOTING OR ACIDISING	☐	ABANDONMENT*	☐
REPAIR WELL	☒	CHANGE PLANT	☐	(Other)	☐		☐
(Other)	☐		☐	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)			

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Set packer in 5-1/2" casing at 4890' above completion perforations 4900'-4933'.
Detected hole in 5-1/2" casing above packer. Found hole at 3725'.

Set retrievable packer in 5-1/2" casing at 3807'. Filled with sand to 3740'.
Cemented hole at 3725' with Class "H" cement with 2% each. Drilled cement out to 3740'. Set packer at 3694' and tested below at 1000# which held. Tested above packer which bled off.

Ran pipe analysis log - 2 copies attached. Indicated corrosion 2884' to 3696' with several possible holes. Testing confirmed casing leak. Shut down. Well idle.

Present Operation: Waiting on program to continue repair.

RECEIVED
AUG 06 1985
OIL CON. DIV.
DIST. 3

18. I hereby certify that the foregoing is true and correct

SIGNED <u>W. O. Whitman</u>	TITLE <u>STAFF ENGINEER</u>	DATE <u>7/ /85</u>
(This space for Federal or State office use)		
APPROVED BY _____	TITLE _____	ACCEPTED FOR RECORD
CONDITIONS OF APPROVAL, IF ANY:		

AUG 05 1985

*See Instructions on Reverse Side

FARMINGTON RESOURCE AREA

BY Sm

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

NMOCC