5. LEASE

SF_080670

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME San Juan 27-4 Unit
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAME
	San Juan 27-4 Unit
1. oil gas well	9. WELL NO.
2. NAME OF OPERATOR	8/
El Paso Natural Gas Company	10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR	Tapacito Pictured Cliffs
PO Box 4289, Farmington, NM 87499	11. SEC., T., R., M., OR BLK. AND SURVEY OR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	AREA I DA NA
below.)	Sec. 32, T-27-N, R-4-W, NMPM
AT SURFACE: 947'S, 1800'W AT TOP PROD. INTERVAL:	12. COUNTY OR PARISHI 13. STATE RIO Arriba NM
AT TOTAL DEPTH:	Rio Arribal NM 14. API NO.
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	14. AFI NO.
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)
NO. CON P. CO. CO.	7119'
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF	
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF EPACTURE TREAT	
TRACTORE TREAT	1961
SHOOT OR ACIDIZE REPAIR WELL GOOD SHOOT OR ACIDIZE REPAIR WELL	(NOTE; Resort results of multiple completion or zone
PULL OR ALTER CASING	change on Form 9–330.)
MULTIPLE COMPLETE	COLLECTOR AND
CHANGE ZONES	•
ABANDON*Evaluation in Progress	•
(blild)	
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is demanded and true vertical depths for all markers and zones pertined. Production from the subject well hat 31 MCF/D for the ninety day evaluat well to the pre-casing leak average currently evaluating the economics well.	directionally drilled, give subsurface locations and not to this work.)* s ben regained; it averaged ion period. This compares of 36 MCF/D. We are
If the economics are favorable, the repaired. If the economics are not will be plugged and abandoned.	n this well will be permanently favorable, then this well
It is hereby requested to continue in its temporarily repaired state f conditions improve, whichever time	or one year, or until market is lesser. / 1983
Subsurface Safety Valve: Manu. and Type	in fill My 19 Set @ Ft.
18. I hereby certify that the foregoing is true and correct	7
SIGNED William Helack TITLE Prod. Engr.	December 15, 1982
(This space for Federal or State of	fice use)
ADDROVED TO	DATE
CONDITIONS OF APPROVAL IF ANY	

DISTRICT ENGINEER

*See Instructions on Reverse Side