


Form 9-331a
(Feb. 1951)

(SUBMIT IN TRIPLICATE)
UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office _____

Lease No. SF 080511

Unit _____



SUNDRY NOTICES AND REPORTS ON WELLS

| | |
|--|--|
| NOTICE OF INTENTION TO DRILL _____ | SUBSEQUENT REPORT OF WATER SHUT-OFF <u>Surface</u> <input checked="" type="checkbox"/> |
| NOTICE OF INTENTION TO CHANGE PLANS _____ | SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING _____ |
| NOTICE OF INTENTION TO TEST WATER SHUT-OFF _____ | SUBSEQUENT REPORT OF ALTERING CASING _____ |
| NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL _____ | SUBSEQUENT REPORT OF REDRILLING OR REPAIR _____ |
| NOTICE OF INTENTION TO SHOOT OR ACIDIZE _____ | SUBSEQUENT REPORT OF ABANDONMENT _____ |
| NOTICE OF INTENTION TO PULL OR ALTER CASING _____ | SUPPLEMENTARY WELL HISTORY _____ |
| NOTICE OF INTENTION TO ABANDON WELL _____ | |

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Sept. 3, 1952, 19____

Well No. Har. 2 is located 990 ft. from N line and 990 ft. from W line of sec. 31

NW 1/4 31 27 N 7W New Mexico
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)

(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudlogging jobs, cementing points, and all other important proposed work)

100 8 5/8" Cemented 150 sacks. cemented to surface; circulated.
Pipe test: Used pump, 1000 lbs pressure and held there for 15 min. to see if there would be any decline in pressure

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company M. J. Florance

Address Aztec, N. M.

By [Signature]
Title owner