NO. OF COPIES RECEIVED		Form C-103
DISTRIBUTION		Supersedes Old C-102 and C-103
SANTAFE	NEW MEXICO OIL CONSERVATION COMMISSION	Effective 1-1-65
FILE		5a. Indicate Type of Lease
U.S.G.S.		State X Fee
LAND OFFICE	<del> </del>	5. State Oil & Gas Lease No.
OPERATOR		E-289-29
SUNDRY NOTICES AND REPORTS ON WELLS  (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)		
OIL GAS WELL	OTHER-	7. Unit Agreement Name Rincon Unit
2. Name of Operator El Paso Natural Gas Company		8. Farm or Lease Name Rincon Unit
3. Address of Operator	0.001	9. Well No.
	armington, New Mexico 87401	131
4. Location of Well	2 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	· 1
UNIT LETTERK	1800 FEET FROM THE South LINE AND 1550 FEET FR	" TITITITIES TO AND TO THE TOTAL ME
THE West Line, SECTION 36 TOWNSHIP 27N RANGE 7W NMPM.		
	15. Elevation (Show whether DF, RT, GR, etc.)	12. County
	6552' GL	Rio Arriba
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  NOTICE OF INTENTION TO:  SUBSEQUENT REPORT OF:		
	PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
PERFORM REMEDIAL WORK	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	CHANGE PLANS CASING TEST AND CEMENT JQB	<u> </u>
PULL ON ALVEN CACING	OTHER	
OTHER Temporarily isolate casing failure X		
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.		
A packer was set on August 15, 1980 above Dakota perforations at 7164' to effect a temporary repair of a casing failure. The well will be produced for 90 days to determine if production warrants squeeze cementing the casing failure.  AUG 2 2 1980 OIL COM. DIST. 3		
18. I hereby certify that the info	nation above is true and complete to the best of a knowledge and belief.	DATE 8-18-80
SIGNED (Mans 1)	Charge TITLE Production Engineer	DATE U TO OU
Original Signed b	FRANK T. CHAVEZ.  SUPERVISOR DISTRICT # 3	AUG 22 1980
Wellmust be repaired or phygist out 90 chays		