

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well  gas well  other

2. NAME OF OPERATOR  
El Paso Natural Gas Company

3. ADDRESS OF OPERATOR  
P. O. Box 289, Farmington, N. M. 87401

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)  
AT SURFACE: 1562'N, 1650'E, Sec. 17-27-07  
AT TOP PROD. INTERVAL:  
AT TOTAL DEPTH:

5. LEASE  
SF 078640

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME  
San Juan 28-7 Unit

8. FARM OR LEASE NAME  
San Juan 28-7 Unit

9. WELL NO.  
154

10. FIELD OR WILDCAT NAME  
Basin Dakota

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA  
Sec. 17, T27N, R7W NMPM

12. COUNTY OR PARISH  
Rio Arriba

13. STATE  
New Mexico

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)  
69074 G.L.

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

PULL OR ALTER CASING


MULTIPLE COMPLETE

CHANGE ZONES

ABANDON\*

(other) Extension of evaluation period

SUBSEQUENT REPORT OF



(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

A packer was set in the subject well on October 22, 1980 at a depth of 7562' to effect a temporary repair of a casing failure. Due to equipment problems, the well was not returned to production until Nov. 17, 1980 and subsequent problems cause production data to be incomplete thus making a realistic evaluation of the well's recovery from the failure difficult. Production data will be available Jan. 31, 1981 and an evaluation completed, however, geological recommendations, interest owner's approvals, and equipment availability will extend any remedial action on the well past the initial 90 day approval period. ~~It is therefore requested an extension of 90 days be granted to the procedure.~~

*Extension approved for a 30 day period, until 3/1/81*  
*Wamsley*

Subsurface Safety Valve: Manu. and Type \_\_\_\_\_ Set @ \_\_\_\_\_ Ft.


18. I hereby certify that the foregoing is true and correct

SIGNED James D. Cochran TITLE Production Engineer DATE January 29, 1981

(This space for Federal or State office use)

APPROVED BY: \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY:  
Bruce Wamsley  
for DISTRICT ENGINEER



\*See Instructions on Reverse Side

NMOCC