

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

RECEIVED

MAR 08 1990

OIL CON. DIV.

DIST. 3

Sundry Notices and Reports on Wells

1. Type of Well GAS	5. Lease Number SF-080670
2. Operator <i>MOE</i> <del>El Paso Natural Gas Company</del>	6. If Indian, All.or Tribe Name
3. Address & Phone No. of Operator PO Box 4289, Farmington, NM 87499	7. Unit Agreement Name San Juan 27-4 Unit
4. Location of Well 1930'N, 430'W	8. Farm or Lease Name San Juan 27-4 Unit
	9. Well No. 66
	10. Field, Pool, Wildcat Tapacitos PC
	11. Sec. T. R. M. or Blk Sec. 31, T-27-N, R-04-W NMPM
14. Permit No.	15. Elevations 7301'GR
	12. County Rio Arriba
	13. State NM
16. Intent to/Subsequent Report of : Repair Well	
17. Describe proposed or completed operations:	

The tubing/casing annulus of this well will be pressure tested to 625 psi which is approximatley 100 psi greater than the most current SICP of 512 psi. If pressure declines more than 10% in 15 minutes, the well will be squeeze repaired by:

Mol ru. Kill well as needed. Release packer and tooh. Set sand plug across perfs. Tih w/pkr and test plug to 1500 psi. Locate hole (s) with packer. Shoot squeeze hole 20' below failure. Open bradenhead and circulate cement to surface. WOC 18 hrs. Pick up drill pipe and drill out cmt. Test squeeze to 625 psi. Resqueeze if necessary. Clean out sand plug and unload with nitrogen. Tooh. Tih w/1 1/4" production string and reset packer.

THIS APPROVAL EXPIRES **JUN 04 1990**

18. Authorized by: *Christopher T. Little* 1-22-90  
Regulatory Affairs Date

NOTE: This format is issued in lieu of US BLM Form 3160-5

(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITION OF APPROVAL, IF ANY:

**MAR 05 1990**  
*[Signature]*  
Chief, Branch of  
Mineral Resources  
Farmington Resource Area