UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

Sundry Notices and Reports on Well	ls
1. Type of Well GAS	5. Lease Number SF-079527 6. If Indian, All. or Tribe Name
	7. Unit Agreement Name
2. Name of Operator MERIDIAN OLL 3. Address & Phone No. of Operator	San Juan 27-4 Unit 8. Well Name & Number San Juan 27-4 U 62
PO Box 4289, Farmington, NM 87499 (505) 326-9700	9. API Well No.
4. Location of Well, Footage, Sec., T, R, M 1500'FNL, 800'FWL Sec.26, T-27-N, R-4-W, NMPM	10. Field and Pool
	11. County and State Rio Arriba Co, NM
12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE	
Type of Submission Notice of Intent X Subsequent Report Final Abandonment Type of Act Abandonment Recompletion Plugging Back Casing Repair Altering Casing Other -	change of Plans Change of Plans New Construction Non-Routine Fracturing Water Shut off Conversion to Injectio
This well has been conditioned to a useful function. A tubing freeze was remove produced 68 mcfd from 01-28-94 to 01-29-94. The well logged of optimize production.	ed January 28, 1994. This well ff and the switcher continues to
FEB1 1 1994 OIL CON. DI'DIST. 3	RECEIVED BLM 94 FEB -8 PM 3: 13 070 FARMINGTON, NM
14. I hereby certify that the foregoing is true and consigned (BA) Title Regulatory Affa	airs Date 2/7/94
(This space for Federal or State Office use) APPROVED BY	FEB 0 9 1994°
	RMINGTON DISTRICT OFFICE