

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUBMIT IN TRIPPLICATE\*  
(Other instructions on re-  
verse side)

Form approved.  
Budget Bureau No. 42 R1421.

5. LEASE DESIGNATION AND SERIAL NO.  
SF 080213  
6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT" for such proposals.)

|   |  |  |  |
|---|--|--|--|
| 1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER   |  | 7. UNIT AGREEMENT NAME<br>Rincon Unit  |  |
| 2. NAME OF OPERATOR<br>El Paso Natural Gas Company  |  | 8. FARM OR LEASE NAME<br>Rincon Unit   |  |
| 3. ADDRESS OF OPERATOR<br>P. O. Box 990, Farmington, New Mexico 87401   |  | 9. WELL NO.<br>227   |  |
| 4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*<br>See also space 17 below.)<br>At surface<br><br>1850' S, 2080' E |  | 10. FIELD AND POOL, OR WILDCAT<br>Basin Dakota                                     |  |
| 14. PERMIT NO.  |  | 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA<br>Sec. 28, T-27-N, R-7-W<br>NMPM |  |
| 15. ELEVATIONS (Show whether DF, RT, GR, etc.)<br>6616' GL  |  | 12. COUNTY OR PARISH<br>Rio Arriba   |  |
|   |  | 13. STATE<br>New Mexico  |  |

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON\*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

08-10-77 Spudded well. Drilled surface hole.  
Ran 5 joints 9 5/8", 32.3#, H-40 surface casing, 215' set at 231'.  
Cemented with 236 cu. ft. cement. Circulated to surface. WOC 12 hours;  
held 600#/30 minutes.



18. I hereby certify that the foregoing is true and correct

SIGNED

*A. J. Buico*

TITLE

Drilling Clerk

DATE

August 15, 1977

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY: