Form Approved. Budget Bureau No. 42-R1424

## **UNITED STATES** DEPARTMENT OF THE INTERIOR **GEOLOGICAL SURVEY**

3. LLMSL
SF 078840
6. IF INDIAN, ALLOTTEE OR TRIBE NAME
7. UNIT AGREEMENT NAME
San Juan 28-7 Unit
8. FARM OR LEASE NAME
San Juan 28-7 Unit
9. WELL NO.
237
10. FIELD OR WILDCAT NAME
Basin Dakota
11. SEC., T., R., M., OR BLK. AND SURVEY OR
AREA Sec. 19, T-27-N, R-7-W
NMPM
12. COUNTY OR PARISH 13. STATE
Rio Arriba New Mexico
14. API NO.
15. ELEVATIONS (SHOW DF, KDB, AND WD)

SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME	
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	San Juan 28-7 Unit	
reservoir. Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAME	
1. oil gas 🖂	San Juan 28-7 Unit	
well well other	9. WELL NO.	
2. NAME OF OPERATOR	237	
EL PASO NATURAL GAS CO.	10. FIELD OR WILDCAT NAME	
3. ADDRESS OF OPERATOR	Basin Dakota	
BOX 289 , FARMINGTON, NEW MEXICO	11. SEC., T., R., M., OR BLK. AND SURVEY OR	
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	AREA Sec. 19, T-27-N, R-7-W	
below.)	NMPM	
AT SURFACE: 1690'N, 1180'E	12. COUNTY OR PARISH 13. STATE	
AT TOP PROD. INTERVAL: AT TOTAL DEPTH:	Rio Arriba New Mexico	
AT TOTAL DEFIN.	14. API NO.	
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,		
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)	
	6665' GL	
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	VOOV GIB	
TEST WATER SHUT-OFF 🗌 🔯		
FRACTURE TREAT		
SHOOT OR ACIDIZE	<u>ت</u> ر	
REPAIR WELL	(NOTE: Report results of multiple completion or zone	
PULL OR ALTER CASING U	change on Form 9–330.)	
MULTIPLE COMPLETE	그 그 그 그 그 사람들은 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그	
CHANGE ZONES		
ABANDON*		
(other)		
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly stat including estimated date of starting any proposed work. If well is d measured and true vertical depths for all markers and zones pertiner	irectionally drilled, give subsurface locations and	
10/2/78: Spudded well. Drilled surface hole.		
	그 그 그 그는 그를 가는 것이 하는 것이 없다.	
10/3/78: Ran 5 joints 9 5/8", 32.3# H-40 surf Cemented with 224 cu. ft. cement. Circulated 600#/30 minutes.		
000"/ 30 minutes.		
Subsurface Safety Valve: Manu. and Type		
18. I hereby certify that the foregoing is true and correct	1000	
SIGNED 1 Pused TITLE Drilling Clerk DATE 10/6/78		
(This space for Federal or State office use)		

CONDITIONS OF APPROVAL, IF ANY:

10.25

OCT 1 0 1978

\*See Instructions on Reverse Side

U. S. GEOLOGICAL SURVEY DURANGO, COLO.