UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

5.	LEASE		
	SF	08066	Ŕ

GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	7. UNIT AGREEMENT NAME San Juan 27-4 Unit 8. FARM OR LEASE NAME	
1. oil gas well other 2. NAME OF OPERATOR	San Juan 27-4 Unit 9. WELL NO. 134	
El Paso Natural Gas Company 3. ADDRESS OF OPERATOR Box 289, Farmington, New Mexico 87401 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	10. FIELD OR WILDCAT NAME Blanco M.V. 11. SEC., T., R., M., OR BLK. AND SURVEY OF AREA Sec. 9, T-27-N, R-4-W N.M.P.M. 12. COUNTY OR PARISH Rio Arriba New Mexico 14. API NO.	
below.) AT SURFACE: 1190'S, 1850'W AT TOP PROD. INTERVAL: AT TOTAL DEPTH: 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,		
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD) 6715 ' G.L.	
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL PULL OR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES ABANDON* SUBSEQUENT REPORT OF: SUBSEQUENT REPORT OF:	(NOTE: Report results of multiple completion or zone change on Form 9–330.)	

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

9-10-79: Spudded well. Drilled surface hole.

9-11-79: Ran 5 joints 9 5/8", 36#, KS surface casing 209' set at 223'. Cemented w/295 cu. ft. cement. Circulated to surface. WOC 12 hours; held 600#/30 minutes.

SEP 1 7 1979

*See Instructions on Reverse Side