UNITED STATES

Subsurface Safety Valve: Manu. and Type ____

CONDITIONS OF APPROVAL, IF ANY:

APPROVED BY

18. I hereby certify that the foregoing is true and correct

DEPARTMENT OF THE INTERIOR	SF 079367-A
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a difference or use form 9–331–C for such proposals.)	7. UNIT AGREEMENT NAME Rincon Unit 8. FARM OR LEASE NAME
1. oil gas well other	Rincon Unit 9. WELL NO.
2. NAME OF OPERATOR El Paso Natural Gas Company	100A 10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR	Blanco Mesa Verde
Box 289, Farmington, New Mexico 87401 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space below.)	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 26, T-27-N, R-6-W N.M.P.M.
AT SURFACE: 1800'S, 1850'E AT TOP PROD. INTERVAL:	12. COUNTY OR PARISH 13. STATE Rio Arriba New Mexico
AT TOTAL DEPTH: 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE	14. API NO.
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD) 6648' GL
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF	(NOTE: Report results of multiple completion or zone change on Form 9–330.) state all pertinent details, and give pertinent dates, is directionally drilled, give subsurface locations and
13-80: PBTD 5937'. Tested casing to 3500#, 0 5524,5532,5538,5544,5550,5558,5564,557 5773,5797,5847,5890' w/1 SPZ. Fraced Flushed w/7230 gal. wtr.	8,5614,5627,5644,5681,5695,5750,
14-80: Perfed C.H. & Men 4964,4972,4980,4988, 5142,5178,5184,5219,5247,5318,5344,541 20/40 sand, 148,000 gal. wtr. Flushed	8,5424' W/1 SP 7. Fraced w/) 4 ,000#

5. LEASE

*See Instructions on Reverse Side

(This space for Federal or State office use)

____ TITLE __

Drilling Clerk

_ DATE _

OIL CON. COM.

January 14, 1980

1-2-