DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY	5. LEASE NM-03547 6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.) 1. oil gas well other 2. NAME OF OPERATOR Caulkins Oil Company 3. ADDRESS OF OPERATOR P.O. Box 780 Farmington, New Mexico 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) AT SURFACE: 890' from south& 1120' from east AT TOP PROD. INTERVAL: same AT TOTAL DEPTH: same	7. UNIT AGREEMENT NAME 8. FARM OR LEASE NAME Breech F 9. WELL NO. 11M 10. FIELD OR WILDCAT NAME Blanco Mesa Verde Basin Dakota 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Section 35 27 North 6 West 12. COUNTY OR PARISH Rio Arriba New Mexico 14. API NO.
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF	15. ELEVATIONS (SHOW DF, KDB, AND WD) 6661 GR (NOTE: Report results of multiple completion or zone change on Form 9–330.)
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is dimeasured and true vertical depths for all markers and zones pertinent. Spud at 2:00 PM 6-27 82 Drilled 13 3/4 hole to 320'. Ran 9 5/8" 32.40# New H-40 casis Cemented with 275 sacks Class "CaCl. Plug down 12:00 Midnight Circulated 10 bbls. Slurry to Tested 9 5/8" casing with 600# Minutes. No decrease.	irectionally drilled, give subsurface locations and it to this work.)* Ing to 320' B' cement, 2% 6-27-82. surface.

_ Set @ _ Subsurface Safety Valve: Manu. and Type 18. I hereby certify that the foregoing is true and correct (This space for Federal or State office use) TITLE . DATE . JUL 14 1982

FARMINGTON DISTRICT 5mm