## UNITED STATES

|       | <br> |
|-------|------|
| LEASE |      |

| OMILE SINIES   | 5. LEASE   |
|--|--|
| DEPARTMENT OF THE INTERIOR   | NM Q3547   |
| GEOLOGICAL SURVEY  | 6. IF INDIAN, ÁLLOTTEE OR TRIBE NAME                   |
| SUNDRY NOTICES AND REPORTS ON WELLS  | 7. UNIT AGREEMENT NAME                                 |
| (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)   | 8. FARM OR LEASE NAME                                  |
| 1. oil gas   | Breech F  9. WELL NO.                                  |
| 2. NAME OF OPERATOR  | 11 M   |
| Caulkins Oil Company   | 10. FIELD OR WILDCAT NAME                              |
| 3. ADDRESS OF OPERATOR   | Blanco Mesa Verde Basin Dakota                         |
| P.O. Box 780 Farmington, New Mexico  | 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA       |
| 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17   | Section 35 26 North 6 West                             |
| below.) AT SURFACE: 890 from South & 1120 from East  | 12. COUNTY OR PARISH 13. STATE                         |
| AT TOP PROD. INTERVAL: Same  | Rio Arriba New Mexico                                  |
| AT TOTAL DEPTH: Same   | 14. API NO.  |
| 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,  |  |
| REPORT, OR OTHER DATA  | 15. ELEVATIONS (SHOW DF, KDB, AND WD) 6661 GR.         |
| REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF  | FD   |
| TEST WATER SHUT-OFF   RECEIV   | ED   |
| SHOOT OR ACIDIZE   |  |
| REPAIR WELL  | 82(NOTE: Report results of multiple completion or zone |
| PULL OR ALTER CASING   | change on Form 9–330.)                                 |
| MULTIPLE COMPLETE U CHANGE ZONES U. S. GEOLOGICAL  | SURVEY   |
| ABANDON*  (other) Regarding delinquint report NTL 2B ap  | V. M.  |
| (other) Regarding delinquint report NFE 28 ap  | plication.   |
| 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly statincluding estimated date of starting any proposed work. If well is d measured and true vertical depths for all markers and zones pertiner | irectionally drilled, give subsurface locations and    |
| Well completed ready for production 9  | -28-82.  |
| Well now shut in waiting on pipeline   | connection.  |
| Gas Company of New Mexico report they $1-1-83$ .   | expect to have well tied in by                         |
|  |  |
|  |  |
|  | 10.00  |
|  |  |
|  | 1922   |
|  |  |
| Subsurface Safety Valve: Manu. and Type  | Set @ Ft.  |
| 18. I hereby certify that the foregoing is true and correct  |  |
| SIGNED Charles Dergue TITLE Superinte  | ndent 10-12-82   |
| (This space for Federal or State of  | ice use)   |
| APPROVED BY TITLE  | DATE   |
| CONDITIONS OF APPROVAL, IF ANY:  |  |
|  | Ashebrea dan sisab                                     |
|  | ASSEPTED FOR RECORD                                    |

\*See Instructions on Reverse Side

OCT 18 1982

NMOCC

FARMINGTON SM M